

DEALER ACCOUNT #	0009497	CLAIM STATUS	Paid
GREENEWAY INC		CLAIM	2182226
DBA GREENEWAY RV SALES & SERVICE		CLAIM ORIGIN	WEE
8220 STATE HWY 13 SOUTH		ORIGINAL CLAIM ID	
WISCONSIN RAPIDS, WI 54494		VIN	4X4TPUS26SP104415
USA		CHASSIS VIN	
		MILEAGE	0
		SITE/WAREHOUSE	420 / 420
Labor rate:	\$115.00	ITEM #	PUT403LFT
OWNER INFORMATION		DEALER RO #	11620B
		CLAIM START DATE	01/27/2025
		CLAIM END DATE	05/01/2025
Retail Date of Purchase		WARRANTY EXPIRATION DATE	

Labor																										
Line# 1	<table><tr><td>Operation Code</td><td>Operational Description</td></tr><tr><td>70-671-01-11-003983</td><td>Wall Thermostat - Appliances/Roof AC (GE)/Replace/Electrical</td></tr><tr><td colspan="2">Complaint, Cause, Correction</td></tr><tr><td colspan="2">Original Note : greeneway@dealer-advisors.com, 2025-01-27 10:26:57 :: Complaint: Bedroom thermostat is defective. Cause: Bedroom thermostat has faulty power/mode switch. Pressing with light or heavy pressure doesn't have much of an effect. Rapidly pressing occasionally make it do something, but it isn't working as it should. Correcting: Replace thermostat.</td></tr></table>	Operation Code	Operational Description	70-671-01-11-003983	Wall Thermostat - Appliances/Roof AC (GE)/Replace/Electrical	Complaint, Cause, Correction		Original Note : greeneway@dealer-advisors.com, 2025-01-27 10:26:57 :: Complaint: Bedroom thermostat is defective. Cause: Bedroom thermostat has faulty power/mode switch. Pressing with light or heavy pressure doesn't have much of an effect. Rapidly pressing occasionally make it do something, but it isn't working as it should. Correcting: Replace thermostat.																		
Operation Code	Operational Description																									
70-671-01-11-003983	Wall Thermostat - Appliances/Roof AC (GE)/Replace/Electrical																									
Complaint, Cause, Correction																										
Original Note : greeneway@dealer-advisors.com, 2025-01-27 10:26:57 :: Complaint: Bedroom thermostat is defective. Cause: Bedroom thermostat has faulty power/mode switch. Pressing with light or heavy pressure doesn't have much of an effect. Rapidly pressing occasionally make it do something, but it isn't working as it should. Correcting: Replace thermostat.																										
Model# 1	<table><tr><td>Dlr Sub Hrs</td><td>0.50</td><td>Sub Labor Amt</td><td>\$57.50</td></tr></table>	Dlr Sub Hrs	0.50	Sub Labor Amt	\$57.50																					
Dlr Sub Hrs	0.50	Sub Labor Amt	\$57.50																							
Serial# 1	<table><tr><td>Appr Hrs</td><td>0.50</td><td>Appr Labor Amt</td><td>\$57.50</td></tr></table>	Appr Hrs	0.50	Appr Labor Amt	\$57.50																					
Appr Hrs	0.50	Appr Labor Amt	\$57.50																							
Notes																										
VCB Vendor																										
Part																										
Line# 1	<table><tr><td>Item #</td><td>Description</td></tr><tr><td>F100721350</td><td>THERMOSTAT, WALL, HEAT/COOL, BLACK, #2241-0004 (RVPRODUCTS/COLEMAN)</td></tr><tr><td>Model #</td><td>Serial #</td><td>Part tag</td></tr><tr><td>Sub Qty</td><td>1.00</td><td>Sub Dlr Price</td><td>\$38.61</td><td>Sub Freight</td><td>\$9.23</td></tr><tr><td>Appr Qty</td><td>1.00</td><td>Appr Dlr Price</td><td>\$38.61</td><td>Appr Freight</td><td>\$9.23</td></tr><tr><td colspan="6">Notes</td></tr></table>	Item #	Description	F100721350	THERMOSTAT, WALL, HEAT/COOL, BLACK, #2241-0004 (RVPRODUCTS/COLEMAN)	Model #	Serial #	Part tag	Sub Qty	1.00	Sub Dlr Price	\$38.61	Sub Freight	\$9.23	Appr Qty	1.00	Appr Dlr Price	\$38.61	Appr Freight	\$9.23	Notes					
Item #	Description																									
F100721350	THERMOSTAT, WALL, HEAT/COOL, BLACK, #2241-0004 (RVPRODUCTS/COLEMAN)																									
Model #	Serial #	Part tag																								
Sub Qty	1.00	Sub Dlr Price	\$38.61	Sub Freight	\$9.23																					
Appr Qty	1.00	Appr Dlr Price	\$38.61	Appr Freight	\$9.23																					
Notes																										

Submitted	Labor Amt	\$57.50	Approved	Labor Amt	\$57.50
	Parts & Freight	\$47.84		Parts & Freight	\$47.84
	Total	\$105.34		Total	\$105.34

DEALER	DATE
SIGNATURE	
I certify that I have performed these repairs consistent with Forest River Policies.	

CUSTOMER	DATE
SIGNATURE	
All repairs described have been inspected and are satisfactory.	