



Safety Recall #21V-393

Repair, Claim Preparation & Filing Instructions

Please complete a warranty claim pre-authorization request using the following codes & labor times:

REPAIR

INSTRUCTIONS: Replace the propane (LP) regulator with a non-Winn-Tec LP regulator assembly. Due to supply constraints, regulator brands received may vary. In instances where the pigtails (hose assemblies) are not provided with the replacement regulator, please use the existing hose assemblies. Replace the hoses only if necessary.

LABOR:

Operation Code:	910023
Fault Code:	Recall
Labor Time:	.8 hrs. per unit
Labor time includes .5 hrs. for R&R Regulator and .3 hrs. for LP Pressure Drop test. Follow normal regulator replacement process with drop test.	
Administrative Allowance:	.1 hrs. per unit

PARTS: **P/N 920007**

Promptly submit all pre-authorizations/claims through our Dealer Portal. If you have any questions or need assistance, please call our Technical Service Team at 574-825-9249.

11333 County Road 2, Middlebury, IN 46540
Phone: 574-825-8000, Fax: 574-825-9700
granddesignrv.com