



Warranty Claim Form

Date: 3/28/2025

1127 Greenway RV Sales & Service
8220 State Hwy 13 South
Wisconsin Rapids, WI 54494
United States
Ph. 715-325-5170
mail@greenewayrv.com

General Information

573TE2227P3431431

Imagine 17MKE

Retail Purchase Date: null

Work Started: 3/12/2025

Work Completed: 3/12/2025

Claim Status: Paid

Dealer Work Order #: 11656B

Unit Offline Date: 7/19/2022

Claim #: 881849

Labor: \$57.50

Parts: \$36.84

Shipping: \$0.74

Total: \$95.08

Notes: JPH 3-14-25 Based on details provided, typically speaking this is damage. However, in an effort to assist you in a situation-by-situation basis, I will cover this as a one time only customer courtesy.

Dealer Information

1127 Greenway RV Sales & Service
8220 State Hwy 13 South
Wisconsin Rapids, WI 54494
United States

715-325-5170
mail@greenewayrv.com
Approved Labor Rate: \$115.00

Customer Information

Operation Line # 1

Flat Rate Code: 420059 Solar - Docking Port

Fault Code: Damaged/Maintenance

Problem: Solar roof connector extremely brittle, sealant leaking.

Hours: .5

Cause: Solar roof top connector brittle, connectors broke when getting resealed, replacing with industry standard connectors.

Amount: 57.50

Remedy: R&R roof top solar connector and plugs. Reseal with dicor.

Sublet Repairs: \$0.00

Manufacturer #:

Model #:

Serial #:

<u>Part</u>	<u>Description</u>	<u>Return Tag #</u>	<u>Qty</u>	<u>Units</u>	<u>Amount</u>
420945 SOLAR ROOF TOP ELECTRICAL BOX GEN2 MC4 BLK FSEB30JWO2-BL	SOLAR ROOF TOP ELECTRICAL BOX GEN2 MC4 BLK FSEB30JWO2-BL		1	1	36.84