

FOREST RIVER WARRANTY CLAIM FORM

DEALER ACCOUNT # 0009497
 GREENEWAY INC
 DBA GREENEWAY RV SALES & SERVICE
 8220 STATE HWY 13 SOUTH
 WISCONSIN RAPIDS, WI 54494
 USA

CLAIM STATUS Paid
 CLAIM 2232719
 CLAIM ORIGIN WEB
 ORIGINAL CLAIM ID
 VIN 4X4FCRL2XSS234490
 CHASSIS VIN
 MILEAGE 0
 SITE/WAREHOUSE 020 / 020
 ITEM # CRF35RL
 DEALER RO # 11781B
 CLAIM START DATE 03/18/2025
 CLAIM END DATE 03/18/2025

Labor rate: \$115.00
 OWNER INFORMATION

Retail Date of Purchase WARRANTY EXPIRATION DATE

Claim Line Details

Labor

Line# 1 **Operation Code** **Operational Description**
 20-46-19-00-000721 Window - Exterior/Windows/Reseal/No Tread Code
Complaint, Cause, Correction
 Original Note : greeneway@dealer-advisors.com, 2025-03-18 08:45:37 :: Complaint: The seal around the very rear window is beginning to shrink. Cause: Rear window seal has shrunk. Correction: Replace rear window seal.

Model#	Dlr Sub Hrs	0.50	Sub Labor Amt	\$57.50
Serial#	Appr Hrs	0.30	Appr Labor Amt	\$34.50

Notes
 SENT TO VENDOR FOR REVIEW
 PER VENDOR

Case Number: 5702833
 VIN: SS234490

Hello Morgan Underwood,
 Thank you for contacting Lippert Customer Care Center.

We have reviewed your request and information provided and Lippert will authorize 0.3 hours of labor to reinstall the window glazing.

Part

Line# 1	Item #	Description			
	USERPART	580209- Window glazing seal black large			
	Model #	Serial #	Part tag		
	Sub Qty	7.00	Sub Dlr Price	\$15.82	Sub Freight \$1.75
	Appr Qty	7.00	Appr Dlr Price	\$15.82	Appr Freight \$1.75

Notes

Submitted	Labor Amt	\$57.50	Approved	Labor Amt	\$34.50
	Parts & Freight	\$17.57		Parts & Freight	\$17.57
	Total	\$75.07		Total	\$52.07

DEALER _____ DATE _____
 SIGNATURE
 I certify that I have performed these repairs consistent with Forest River Policies.

CUSTOMER _____ DATE _____
 SIGNATURE
 All repairs described have been inspected and are satisfactory.