

GREENEWAY, INC.
8220 STATE HWY 13 SOUTH
WISCONSIN RAPIDS WI
US
54494
(715) 325-5170

WORK ORDER # 11814B

Date In:	04 APR 25	Author:	KOTT
Promised Date:	25 DEC 25	Stock No:	11321
:	:	Year:	2025
Customer Name:	17590 - FAUGHT, JASON	Manufacturer:	GRAND DESIGN
Address:	N1708 6TH AVENUE PO BO	Brand:	MOMENTUM G-CLASS
:	COLOMA, WI	Model:	415G
Postal/Zip:	54930	Miles/Hrs:	0
Phone#(res):	9204206815	Exterior Color:	:
Phone#(bus):	:	Unit Type:	FWH-FW TOY HAULER
Cell Phone:	:	License#:	:
Email:	HAPPYHOURS4@HOTMAIL.CO	Tag#:	:
Purchased Date:	14 JAN 25	:	:
Delivery Date:	14 APR 25	:	:
InService Date:	:	:	:
Serial#:	573FM4731SBB03873	:	:

```
*****
Job #   Description                JOB INFORMATION                Type Bill To
*****
WARR    COMPLAINT:  WARRANTY REPAIR 1 - Vent fan control          W    1020    GRAND
          dropped out of ohc bottom panel in
          kitchen
          CAUSE:      One screw was not drilled into the panel
          CORRECTION: Reinstalled both screws now both are
          screwed into panel REQUESTING .1
WARR    COMPLAINT:  WARRANTY REPAIR 2 -Kitchen faucet does       W    1020    GRAND
          not retract as it should
          CAUSE:      Subpar product weight
          CORRECTION: Does not matter where weight is put on
          the line it does not retract the hose
          back up REQUESTING .2
WARR    COMPLAINT:  WARRANTY REPAIR 4 - On the walls             W    1020    GRAND
          throughout the unit there are smudges
          and dirt marks
          CAUSE:      Mfg
          CORRECTION: Used Murphy's oil soap to clean off
          spots on the wall REQUESTING .2
WARR    COMPLAINT:  WARRANTY REPAIR 5 -The door to bedroom      W    1020    GRAND
          is not lying flush it does open and
          close properly and you only see the door
          not lying flush from the bedroom side
          CAUSE:      Mfg
          CORRECTION: I added a couple nails to the top of
          doorway trim to help with the door
          looking uneven it opens and closes as it
          should so that's all I can do as far as
```

Continued on page 2

Work Order : 11814B

```

*****
Job #   Description           JOB INFORMATION           Type Bill To
*****
WARR    COMPLAINT:           it looking uneven REQUESTING .1
WARRANTY REPAIR 3 - Ceiling in garage   W    1020    GRAND
has a black mark and in hall up near
bathroom there are some smudges on the
ceiling
CAUSE:      Mfg in the unit
CORRECTION: used cleaner and quick solve to remove
black marks and I cleaned all white trim
strips on ceiling throughout unit they
had a scrape in center on all 9 ceiling
trim REQUESTING .5
WARR    COMPLAINT:           WARRANTY REPAIR 6 -The bedrooms   W    1020    GRAND
headboard looks off kilter
CAUSE:      Mfg installed it cockeyed
CORRECTION: Removed the screws and adjusted the
headboard this took awhile it's a pain
holding leveling REQUESTING 1 HOUR
WARR    COMPLAINT:           WARRANTY REPAIR 8 -Base of toilet has   W    1020    GRAND
something coming from beneath it
CAUSE:      Debri left by mfg
CORRECTION: I carefully cut away the debri
REQUESTING .1
WARR    COMPLAINT:           WARRANTY REPAIR 9 - the lino and garage W    1020    GRAND
floor have putty and a sticky substance
ground in to it
CAUSE:      Mfg
CORRECTION: I used quick solve DND a brush to remove
the putty and silicone that was ground
in REQUESTING .6

```

```

*****
Job#  Lab Code  Description  LABOUR  Mech Bill to  Hrs  Rate  Total
*****
ARR01 Z992      MISC LABOUR CODE (WARR HOD W-1020  0.50  140.00  70.00
ARR02 Z992      MISC LABOUR CODE (WARR HOD W-1020  0.50  140.00  70.00
ARR04 Z992      MISC LABOUR CODE (WARR HOD W-1020  0.50  140.00  70.00
ARR05 Z992      MISC LABOUR CODE (WARR HOD W-1020  0.50  140.00  70.00
ARR03 Z992      MISC LABOUR CODE (WARR HOD W-1020  0.12  140.00  16.80
ARR03 Z992      MISC LABOUR CODE (WARR HOD W-1020  0.38  140.00  53.20
ARR06 Z992      MISC LABOUR CODE (WARR HOD W-1020  0.00  140.00  0.00
ARR06 Z992      MISC LABOUR CODE (WARR HOD W-1020  0.50  140.00  70.00
ARR08 Z992      MISC LABOUR CODE (WARR HOD W-1020  0.50  140.00  70.00
ARR09 Z992      MISC LABOUR CODE (WARR HOD W-1020  0.50  140.00  70.00

```

```

*****
Job #  Excode  Description  EXTRAS  bill to  Qty  Price  Total
*****
ARR01  SSE      SHOP SUPPLIES - EXTERNAL  W-1020  1.00  0.00  0.00

```

Continued on page 3

Work Order : 11814B

BILLINGS SUMMARY

Type	Bill Id	Parts	Labour	Sublet	Extras	Tax	Total
W	1020	0.00	560.00	0.00	0.00	0.00	560.00
	Totals	0.00	560.00	0.00	0.00	0.00	560.00

&k2S
&k0S