

GREENEWAY, INC.  
8220 STATE HWY 13 SOUTH  
WISCONSIN RAPIDS WI  
US  
54494  
(715) 325-5170

WORK ORDER # 11846B

Date In: 21 APR 25 Author: KOTT  
Promised Date: 04 JUL 25 Stock No: 11350  
: Year: 2025  
Customer Name: 17660 - SWIGGUM, KEVIN Manufacturer: GRAND DESIGN  
Address: 5909 SHARPSBURG DR #53 Brand: IMAGINE XLS  
: MADISON, WI Model: 22MLE  
Postal/Zip: 53718 Miles/Hrs: 0  
Phone#(res): 6086588684 Exterior Color:  
Phone#(bus): Unit Type: TT-TRAVEL TRAILER  
Cell Phone: License#:  
Email: KSWIGGUM@GMAIL.COM Tag#:  
Purchased Date: 25 MAR 25 :  
Delivery Date: 21 APR 25 :  
InService Date: :  
Serial#: 573TE2624S3442437 :

\*\*\*\*\*  
Job # Description JOB INFORMATION Type Bill To  
\*\*\*\*\*  
8 COMPLAINT: FRIDGE DOOR NOT LATCHING PROPERLY W 1020 GRAND  
CAUSE: Daf. The door will not close easily  
CORRECTION: So I adjusted the door a bit it now  
shuts like it should no catching nice  
and easy it closes REQUESTING .2  
DAF COMPLAINT: DAF-WARRANTY REPAIRS- 1- SLIDE SPITTERS I PDI PRE-D  
WHEN GOING IN 2- HAD TO MANUALLY MOVE  
AWNING WHEN EXTENDING 3- CIRCLE  
COMPARTMENT LIGHTS DON'T WORK 4- CABINET  
DOOR IN BATHROOM NOT ALIGNED 5- CENTER  
CONSOLE LOSE 6- KITCHEN SHADE DOES NOT  
GO UP  
CAUSE: Daf  
CORRECTION: Will be on own line with info if a  
problem or if npf  
WARR COMPLAINT: WARRANTY REPAIR 1 - THE SLIDEOUT SPITTER W 1020 GRAND  
HARD WHEN BEING BROUGHT IN  
CAUSE: Daf  
CORRECTION: This is not a schwintek it's a slim rack  
and they are very loud compared to  
others so npf  
WARR COMPLAINT: WARRANTY REPAIR 2 - WHEN EXTENDING THE W 1020 GRAND  
AWNING, I HAD TO MANUALLY MOVE THE ARMS  
3 DIFFERENT TIMES TO GET IT TO EXTEND  
PROPERLY  
CAUSE: Daf  
CORRECTION: This is a new style of awning with  
handles and it needs to be worked a few

Continued on page 2

Work Order : 11846B

```
*****
Job #   Description           JOB INFORMATION           Type Bill To
*****
times to work smoothly
WARR    COMPLAINT:  WARRANTY REPAIR 3 - THERE ARE SMALL           W    1020   GRAND
          CIRCLE LIGHTS IN THE FRONT COMPARTMENT
          THAT DO NOT WORK
          CAUSE:      Daf
          CORRECTION: The small circle lights are actually
                    motion detectors for the strip lights in
                    the compartment . Nothing wrong with it
WARR    COMPLAINT:  WARRANTY REPAIR 4 - THERE IS A CABINET           W    1020   GRAND
          DOOR IN THE BATHROOM NEXT TO THE TOILET
          THAT PETRUDES OUT SLIGHTLY. MAY NOT BE
          ALIGNED RIGHT
          CAUSE:      Daf
          CORRECTION: I pushed it in a bit nothing to
                    noticeable NPF
WARR    COMPLAINT:  WARRANTY REPAIR 5 - CENTER CONSOLE IS           W    1020   GRAND
          LOOSE
          CAUSE:      Daf loose from mfg
          CORRECTION: So I want this noted with mfg , I did
                    remove the. Center piece and tightened
                    all screws for the lifting mechanism
                    then reinstalled if customer would
                    happen to not like that it wiggles a bit
                    it will have been noted and a pic of tag
                    and the center have also been taken . I
                    reattached frame of the recliners to the
                    floorth REQUESTING .5
WARR    COMPLAINT:  WARRANTY REPAIR 6 - KITCHEN SHADE WILL           W    1020   GRAND
          NOT RETRACT
          CAUSE:      Daf
          CORRECTION: I adjusted the shades wheel a bit it now
                    goes up as it should REQUESTING .1
WARR    COMPLAINT:  WARRANTY REPAIR 7 - TRIM MISSING UNDER           W    1020   GRAND
          THE CABINETS ABOVE KITCHEN SINK
          CAUSE:      Daf
          CORRECTION: So the bottom cuts on the wood stiles
                    are not finished so this is normal
WARR    COMPLAINT:  WARRANTY REPAIR 8 - PRIVACY CURTAIN IS           W    1020   GRAND
          STAINED
          CAUSE:      Daf
          CORRECTION: I used a wet cloth to remove the stain
                    it looked like a muddy shoe hit the
                    curtain REQUESTING .1
WARR    COMPLAINT:  WARRANTY REPAIR 9 - the table edge looks W           1020   GRAND
          as though it's peeling
          CAUSE:      Peeling edge
          CORRECTION: I used sand paper and removed the
                    peeling edge REQUESTING .1
*****
```

Continued on page 3

Work Order : 11846B

```
*****
Job#  Lab Code  Description  LABOUR  Mech Bill to    Hrs    Rate    Total
*****
   8  WARR      MANUFACTURER WARRANTY  HOD  W-1020    0.31   140.00   43.40
   8  WARR      MANUFACTURER WARRANTY  HOD  W-1020    0.19   140.00   26.60
  DAF  Z991      DAF-WARRANTY REPAIR    HOD  I-PDI     0.10    70.00    7.00
ARR01 Z992      MISC LABOUR CODE (WARR HOD  W-1020    0.50   115.00   57.50
ARR02 Z992      MISC LABOUR CODE (WARR HOD  W-1020    0.50   115.00   57.50
ARR03 Z992      MISC LABOUR CODE (WARR HOD  W-1020    0.50   115.00   57.50
ARR04 Z992      MISC LABOUR CODE (WARR HOD  W-1020    0.50   115.00   57.50
ARR05 Z992      MISC LABOUR CODE (WARR HOD  W-1020    0.21   115.00   24.15
ARR05 Z992      MISC LABOUR CODE (WARR HOD  W-1020    0.29   115.00   33.35
ARR06 Z992      MISC LABOUR CODE (WARR HOD  W-1020    0.50   115.00   57.50
ARR07 Z992      MISC LABOUR CODE (WARR HOD  W-1020    0.50   115.00   57.50
ARR08 Z992      MISC LABOUR CODE (WARR HOD  W-1020    0.50   115.00   57.50
ARR09 Z992      MISC LABOUR CODE (WARR HOD  W-1020    0.50   140.00   70.00
*****
```

```
*****
Job #  Excode  Description  EXTRAS  bill to    Qty    Price    Total
*****
ARR09  SSE      SHOP SUPPLIES - EXTERNAL  W-1020    1.00    0.00    0.00
*****
```

```
*****
                        BILLINGS SUMMARY
Type Bill Id      Parts    Labour    Sublet    Extras    Tax    Total
*****
I   PDI            0.00     7.00     0.00     0.00     0.00     7.00
W   1020           0.00    600.00     0.00     0.00     0.00    600.00

      Totals      0.00    607.00     0.00     0.00     0.00    607.00
*****
```

&k2S  
&k0S