

GREENEWAY, INC.
8220 STATE HWY 13 SOUTH
WISCONSIN RAPIDS WI
US
54494
(715) 325-5170

WORK ORDER # 11878B

Date In:	24 APR 25	Author:	KOTT
Promised Date:	01 MAY 25	Stock No:	11319
:	:	Year:	2025
Customer Name:	17594 - TRENT, JOHN	Manufacturer:	FOREST RIVER
Address:	W9480 COUNTY RD S	Brand:	FLAGSTAFF CLASSIC FW
:	NEW LONDON, WI	Model:	374DBH
Postal/Zip:	54961	Miles/Hrs:	0
Phone#(res):	9207160643	Exterior Color:	:
Phone#(bus):	:	Unit Type:	FW-FIFTH WHEEL
Cell Phone:	:	License#:	:
Email:	JTRENT1@GMAIL.COM	Tag#:	:
Purchased Date:	17 JAN 25	:	:
Delivery Date:	01 MAY 25	:	:
InService Date:	:	:	:
Serial#:	4X4FFLN22S1908672	:	:

Job #	Description	JOB INFORMATION	Type	Bill To
WARR	COMPLAINT:	WARRANTY REPAIR 1 - Missing the cover on W awning arm rear most awning the back arm	1021	FORES
	CAUSE:	Missing awning arm cover		
	CORRECTION:	Obtained a cover from parts it's off of a extra awning arm so no part number attached REQUESTING .3		
WARR	COMPLAINT:	WARRANTY REPAIR 2 - The curtain bracket W in the bedroom ds bis not attached to the wall	1021	FORES
	CAUSE:	Improper install		
	CORRECTION:	Installed 2 screws to curtain bracket and installed curtain REQUESTING .1		
WARR	COMPLAINT:	WARRANTY REPAIR 3 - The black and grey 1 W are switched while filling the toilet it reads on grey one	1021	FORES
	CAUSE:	Mfg hooked up the black and grey 1 wires backwards so grey reads black black reads grey 1		
	CORRECTION:	Removed the panels to access wires moved the black wire and grey wire around tested now monitor is reading correctly reinstalled the panels then filled all tanks to full to ensure they were reading accurately and they are REQUESTING .5		
WARR	COMPLAINT:	WARRANTY REPAIR 4 - cover for awning arm W is missing	1021	FORES
	CAUSE:	Missing Please order new black cover for		

Continued on page 2

Work Order : 11878B

```

*****
Job #      Description      JOB INFORMATION      Type Bill To
*****
              rear awning arms top cover the one from
              parts did not fit
CORRECTION: REQUESTING .3

```

```

*****
Job#  Lab Code  Description  LABOUR  Mech Bill to  Hrs  Rate  Total
*****
ARR01 Z992      MISC LABOUR CODE (WARR HOD W-1021  0.50  140.00  70.00
ARR02 Z992      MISC LABOUR CODE (WARR HOD W-1021  0.47  140.00  65.80
ARR02 Z992      MISC LABOUR CODE (WARR HOD W-1021  0.03  140.00   4.20
ARR03 Z992      MISC LABOUR CODE (WARR HOD W-1021  0.27  140.00  37.80
ARR03 Z992      MISC LABOUR CODE (WARR HOD W-1021  0.13  140.00  18.20
ARR03 Z992      MISC LABOUR CODE (WARR HOD W-1021  0.03  140.00   4.20
ARR03 Z992      MISC LABOUR CODE (WARR HOD W-1021  0.07  140.00   9.80
ARR04 Z992      MISC LABOUR CODE (WARR HOD W-1021  0.50  140.00  70.00

```

```

*****
Job #  Excode  Description  EXTRAS  bill to  Qty  Price  Total
*****
ARR01  SSE     SHOP SUPPLIES - EXTERNAL  W-1021  1.00  0.00  0.00

```

```

*****
                        BILLINGS SUMMARY
Type Bill Id      Parts      Labour      Sublet      Extras      Tax      Total
*****
W      1021          0.00      280.00          0.00          0.00          0.00      280.00

              Totals          0.00      280.00          0.00          0.00          0.00      280.00

```

&k2S
&k0S