



Warranty Claim Form

Date: 5/9/2025

1127 Greenway RV Sales & Service
8220 State Hwy 13 South
Wisconsin Rapids, WI 54494
United States
Ph. 715-325-5170
mail@greenwayrv.com

General Information

573FR3721N9919784
Reflection 337RLS
Retail Purchase Date: 6/18/2022
Work Started: 4/28/2025
Work Completed: 4/28/2025

Claim Status: Paid
Dealer Work Order #: 11931
Unit Offline Date: 3/10/2022

Claim #: 894215
Labor: \$196.00
Parts: \$48.02
Shipping: \$2.37
Total: \$246.39

Notes:

Dealer Information

1127 Greenway RV Sales & Service
8220 State Hwy 13 South
Wisconsin Rapids, WI 54494
United States

715-325-5170
mail@greenwayrv.com
Approved Labor Rate: \$140.00

Customer Information

Bacilio Suarez del Real
1005 Brewster Dr Apt 3
Lake Mills, Wisconsin 53551-1787
United States
414-550-0726

Operation Line # 1

Flat Rate Code: 910045 Recalls/Field Campaign - Quick Disconnect *Fault Code:* Recall (supersedes 910029)

Problem: Quick disconnect recall 24v-861

Hours: .8

Cause: Quick disconnect recall 24v-861

Amount: 112.00

Remedy: Remove the two recalled QD's, place teflon tape on new quick disconnect and secured to place

Sublet Repairs: \$0.00

Manufacturer #:

Model #:

Serial #:

<u>Part</u>	<u>Description</u>	<u>Return Tag #</u>	<u>Qty</u>	<u>Units</u>	<u>Amount</u>
220061 QUICK DISCONNECT X 1/4 BRASS SHUT OFF W/PLUG AF	QUICK DISCONNECT X 1/4 BRASS SHUT OFF W/PLUG AF		2	1	48.02

Operation Line # 2

Flat Rate Code: 910031 Recalls/Field Campaign - Lippert Solera *Fault Code:* Recall Awning Weld 910031

Problem: Recall 22v-603 Lippert Solera Awnings

Hours: .6

Cause: Recall 22v-603 Lippert Solera Awnings

Amount: 84.00

Remedy: Inspection of front and back awning was done and both fabric are okay at this time.

Sublet Repairs: \$0.00

Manufacturer #: 1

Model #: 1

Serial #: 1

<u>Part</u>	<u>Description</u>	<u>Return Tag #</u>	<u>Qty</u>	<u>Units</u>	<u>Amount</u>
961751 LIPPERT ONLY	LABOR LIPPERT LABOR ONLY		1	1	0.00