

GREENEWAY, INC.
8220 STATE HWY 13 SOUTH
WISCONSIN RAPIDS WI
US
54494
(715) 325-5170

WORK ORDER # 11942C

Date In:	22 MAY 25	Author:	DLUCAS
Promised Date:	31 MAY 26	Stock No:	11317
:	:	Year:	2025
Customer Name:	15413 - SLAASTED, RALP	Manufacturer:	FOREST RIVER
Address:	180 MILL AVE	Brand:	PUMA DESTINATION
:	UNION GROVE, WI	Model:	403LFT
Postal/Zip:	53182	Miles/Hrs:	0
Phone#(res):	262-321-5404	Exterior Color:	:
Phone#(bus):	:	Unit Type:	TT-TRAVEL TRAILER
Cell Phone:	:	License#:	:
Email:	SLAASTED@SBCGLOBAL.NET	Tag#:	DB: 3/10
Purchased Date:	26 APR 25	:	:
Delivery Date:	23 MAY 25	:	:
InService Date:	:	:	:
Serial#:	4X4TPUS22SP105237	:	:

```
*****
Job #   Description      JOB INFORMATION      Type Bill To
*****
2       COMPLAINT:  STEP RECALL 25V245,2025-203 MORRYDE      W      1021    FORES
        DETACHABLE STEPS. INSPECT AND CORRECT IF
        NEEDED.
        CAUSE:      Recall
        CORRECTION: Replace with new one  Approved .5
1       COMPLAINT:  CUSTOMER STATES THAT THEY WERE NOTICING  W      1021    FORES
        WATER DROPPIGN ABOVE THE WHEELS WHEN HE
        HAD THE TANKS PRESSURIZED- HE ALSO
        NOTICE WATER DRIPPING UNDER THE WATER
        HEATER- NEEDS TO BE DIAGNOSED-
        CAUSE:      The o ring was not properly seated
        properly which caused the hot water line
        in the back of the hot water tank to
        leak
        CORRECTION: Put in a new o ring turn the water back
        on, and I have no leaks  REQ: .50
        Warranty Approved .5
3       COMPLAINT:  ADDED 11/3- CUSTOMER STATES THAT THE      W      1021    FORES
        FURNACE IS NOT OPERATING- SPECIFICALLY
        IN THE BEDROOM- CUSTOMER STATES THAT THE
        FURNACE WILL TURN ON BUT WILL NOT BLOW
        WARM AIR
        CAUSE:      Furnace will not operate in bedroom. The
        thermostat in the bedroom is for the a/c
        only not the furnace. The thermostat in
        the hall is for the furnace has to be
        set to zone 1 and then the furnace works
        in bedroom
```

Continued on page 2

Work Order : 11942C

```

*****
Job #   Description                JOB INFORMATION                Type Bill To
*****
CORRECTION: Furnace will not operate in bedroom. The
              thermostat in the bedroom is for the a/c
              only not the furnace. The thermostat in
              the hall is for the furnace has to be
              set to zone 1 and then the furnace works
              in bedroom   REQ: .10   Warranty Approved
              .10
4        COMPLAINT: CMR STATES THAT THE BEDROOM WINDOW DOES W   1021   FORES
              NOT CLOSE ALL THE WAY- IN THE LOWER LEFT
              CORNER THERE IS A GAP WHEN YOU CLOSE THE
              WINDOW
              CAUSE: 1000 DEFECT FROM MANUFACTURER Window
              does not seal in the left corner   Ti
              will need a new window
              CORRECTION: R&R WINDOW REQ: 2.50   Warranty Approved
              1 Hour
WMH      COMPLAINT: WINTERIZE WATER SYSTEM & TRAPS -SELF   I   PDI   PRE-D
              CONTAINED - MOTORIZED
              CAUSE: Had to on winterize to do my diag
              CORRECTION: Rewinterize

```

```

*****
Job # Part No      Description      PARTS      Bill to      Qty      Price      Total
*****
2      82204078      RECALL KIT MORRYDE STEPS W-1021      1      0.00      0.00
1      742979164351  SINGLE 1/2" SWIVEL SEAL W-1021      1      1.91      1.91
4      8220341A      WINDOW 30"X22" EMERGENCY W-1021      1      75.08      75.08
WMH    009114950003  -50 F GLYCERIN FREE BASE I-PDI      3      4.80      14.40
4      677917009992  BUTYL TAPE GREY W-1021      1      9.54      9.54
4      161128        NOVAFLEX PRO 10 OZ TRANS W-1021      1      9.28      9.28

```

```

*****
Job# Lab Code Description LABOUR Mech Bill to Hrs Rate Total
*****
2 WARR MANUFACTURER WARRANTY JL W-1021 0.39 140.00 54.60
2 WARR MANUFACTURER WARRANTY JL W-1021 0.11 140.00 15.40
1 WARR MANUFACTURER WARRANTY TD W-1021 0.00 140.00 0.00
1 WARR MANUFACTURER WARRANTY JL W-1021 0.09 140.00 12.60
1 WARR MANUFACTURER WARRANTY JL W-1021 0.21 140.00 29.40
1 WARR MANUFACTURER WARRANTY JL W-1021 0.20 140.00 28.00
3 WARR MANUFACTURER WARRANTY JL W-1021 0.10 140.00 14.00
4 WARR MANUFACTURER WARRANTY TD W-1021 0.36 140.00 50.40
4 WARR MANUFACTURER WARRANTY JL W-1021 0.14 140.00 19.60
WMH W495 WINTERIZE RV (WATER SY JL I-PDI 1.40 70.00 98.00
WMH W495 WINTERIZE RV (WATER SY JL I-PDI 0.00 70.00 0.00

```

Continued on page 3

Work Order : 11942C

```

*****
Job #  Excode   Description   EXTRAS      bill to    Qty    Price    Total
*****
   4   FRT      FREIGHT          W-1021    1.00    53.33    53.33
WMH   SSE      SHOP SUPPLIES - EXTERNAL  I-PDI    1.00     0.00     0.00
*****

```

```

*****
                        BILLINGS SUMMARY
Type Bill Id      Parts    Labour    Sublet    Extras      Tax      Total
*****
I    PDI          14.40     98.00     0.00      0.00      0.00    112.40
W    1021         95.81    224.00     0.00     53.33      0.00    373.14

      Totals      110.21    322.00     0.00     53.33      0.00    485.54

```

&k2S

&k0S