



Warranty Claim Form

Date: 8/20/2025

1127 Greenway RV Sales & Service
8220 State Hwy 13 South
Wisconsin Rapids, WI 54494
United States
Ph. 715-325-5170
mail@greenewayrv.com

General Information

573TE3022S6654623

Imagine 2600RB

Retail Purchase Date: null

Work Started: 7/28/2025

Work Completed: 7/28/2025

Claim Status: Paid

Dealer Work Order #: 11954

Unit Offline Date: 4/4/2025

Claim #: 920197

Labor: \$112.00

Parts: \$5.60

Shipping: \$0.00

Total: \$117.60

Notes: -adjusted SS to 5% of approved labor. NN 8.19 AB 8/7 *Please hold all parts for a minimum of 30 days after the claim is paid*

Dealer Information

1127 Greenway RV Sales & Service
8220 State Hwy 13 South
Wisconsin Rapids, WI 54494
United States

715-325-5170
mail@greenewayrv.com
Approved Labor Rate: \$140.00

Customer Information

Operation Line # 1

Flat Rate Code: 590046 Roof Vents - Reseal

Fault Code: Improper Installation/Build

Problem: The dicor around the kitchen and bedroom vents have small holes/bubbles.

Hours: .2

Cause: There were some bubbles, small holes in the dicor around the kitchen and bedroom vent.

Amount: 28.00

Remedy: Re-dicored the vents.

Sublet Repairs: \$0.00

Manufacturer #:

Model #:

Serial #:

Operation Line # 2

Flat Rate Code: 110002 Frame Rails - Touch Up

Fault Code: Damaged/Maintenance

Problem: There are 2 rust spots on both sides of the frame behind the sewer hose. *no sure on labor code. 0.4 hour to fix.

Hours: .4

Cause: There were two rust spots on the frame behind the sewer hose,

Amount: 56.00

Remedy: Sanded away the rust and painted over it.

Sublet Repairs: \$0.00

Manufacturer #: 1

Model #: 1

Serial #: 1

Operation Line # 3

Flat Rate Code: 670019 Sealing - Reseal Countertop (all)

Fault Code: Improper Installation/Build

Problem: The silicone on the bathroom counter on the back wall is not fully sealed.

Hours: .2

Cause: Not sealed correctly from manufacturer.

Amount: 28.00

Remedy: Went over with silicone.

Sublet Repairs: \$0.00

Manufacturer #:

Model #:

Serial #:

<u>Part</u>	<u>Description</u>	<u>Return Tag #</u>	<u>Qty</u>	<u>Units</u>	<u>Amount</u>
960204 Miscellaneous Part for claim use only	Miscellaneous Part for claim use only		1	1	5.60