



Warranty Claim Form

Date: 5/28/2025

1127 Greenway RV Sales & Service
8220 State Hwy 13 South
Wisconsin Rapids, WI 54494
United States
Ph. 715-325-5170
mail@greenwayrv.com

General Information

573TT2012S8832588
Transcend 151RB
Retail Purchase Date: 10/19/2024
Work Started: 5/13/2025
Work Completed: 5/13/2025

Claim Status: Paid
Dealer Work Order #: 12025
Unit Offline Date: 7/8/2024

Claim #: 897649
Labor: \$42.00
Parts: \$0.00
Shipping: \$0.00
Total: \$42.00

Notes:

Dealer Information

1127 Greenway RV Sales & Service
8220 State Hwy 13 South
Wisconsin Rapids, WI 54494
United States

715-325-5170
mail@greenwayrv.com
Approved Labor Rate: \$140.00

Customer Information

ANN CAMPANELLA
902 10TH AVE
HANCOCK, Wisconsin 54943
United States
6084740196

Operation Line # 1

Flat Rate Code: 650030 Bed Base - Repair Base

Fault Code: Damaged/Maintenance

Problem: Customer states the leg for the murphy bed fell off. They think a hole for a screw has stripped out.

Hours: .3

Cause: Over tightening at factory.

Amount: 42.00

Remedy: Replaced with one size larger diameter screw. Tightened nicely.

Sublet Repairs: \$0.00

Manufacturer #:

Model #:

Serial #: