

GREENEWAY, INC.
8220 STATE HWY 13 SOUTH
WISCONSIN RAPIDS WI
US
54494
(715) 325-5170

WORK ORDER # 12066

Date In:	19 MAY 25	Author:	MGRAY
Promised Date:	07 JUL 25	Stock No:	10473
:	:	Year:	2023
Customer Name:	1021 - FOREST RIVER	Manufacturer:	FOREST RIVER
Address:	21815 NETWORK PLACE	Brand:	FLAGSTAFF SUPER-LITE T
:	CHICAGO, IL	Model:	29RBS
Postal/Zip:	60673-1218	Miles/Hrs:	0
Phone#(res):	219-534-3167	Exterior Color:	:
Phone#(bus):	219-534-3167	Unit Type:	TT-TRAVEL TRAILER
Cell Phone:	:	License#:	:
Email:	NONE	Tag#:	:
Purchased Date:	09 MAY 24	:	:
Delivery Date:	23 MAY 24	:	:
InService Date:	:	:	:
Serial#:	4X4TFLE23PZ185412	:	:

```
*****
Job #   Description      JOB INFORMATION      Type Bill To
*****
WARR    COMPLAINT:  WARRANTY REPAIR 1 - Water is leaking      W    1021    FORES
        from under the sink. There is water
        damage on the kitchen cupboard and
        flooring.
        CAUSE:      I ran hot and cold water through the
        water lines and I'm not seeing anything
        leaking. I filled both sink tubs to
        check the drains and still no leaks. I
        left the lines pressurized for three
        days and no leaks have shown up yet.
        There was a leak of some sort at one
        time because two styles were damaged.
        Two styles will need to be replaced and
        we will need a sheet of paneling. The
        manufacturer has a lot of staples in the
        paneling so the chances of it coming off
        in one piece are pretty slim. 5-6 hours
        to fix depending on how everything comes
        apart and if I have to wrap the styles
        myself with the cheap wrap that creases
        from air touching it that the
        manufacturer sends.
        CORRECTION:  ...
WARR    COMPLAINT:  WARRANTY REPAIR 2 - CMR WAS FLUSHING      W    1021    FORES
        BLACK TANK AND WATER STARTED GUSHING OUT
        OF THE OUTDOOR SHOWER FAUCET. CHECK OUT
        FOR DIAG.
        CAUSE:      Faulty check valve.  I hooked up the
```

Continued on page 2

Work Order : 12066

Job #	Description	JOB INFORMATION	Type	Bill To
-------	-------------	-----------------	------	---------

black tank flush, turned the water on, went inside and I could see water coming out the top of the check valve. I turned the water off, drained the lines, disconnected the valve, hooked the new valve up, and turned the water on to test it and the leak stopped. I dried up the area the best I could and I turned a blower on to help dry everything out. After everything dried out I checked it again and the leaks stopped.

1 CORRECTION: Done.
 COMPLAINT: AWNING WE REPLACED NOW DOES NOT WANT TO I PD GOODW
 COME IN OR OUT PROPERLY. CHECK OUT FOR DIAG.
 CAUSE: NPF. I ran the awning in and out several times and everything is working properly.

WARR CORRECTION: Done.
 COMPLAINT: WARRANTY REPAIR 3 - SHOWER IN MAIN W 1021 FORES
 BATHROOM IS LEAKING.
 CAUSE: NPF with the showermizer but when I was checking for leaks I could hear water dripping under the bathroom sink and when I looked inside I could see the hot and cold fittings were leaking. I drained the water lines, disconnected the hot and cold fittings, checked the seals and they're good. I put thread tape on the fittings, tightened them down and turned the water on to test it. I ran hot and cold water through the lines and the leaks stopped.
 CORRECTION: Done.

Job #	Part No	Description	PARTS	Bill to	Qty	Price	Total
-------	---------	-------------	-------	---------	-----	-------	-------

WARR0	756815001472	VACUUM BREAKER / CHECK V	W-1021		1	33.36	33.36
-------	--------------	--------------------------	--------	--	---	-------	-------

Job#	Lab Code	Description	LABOUR	Mech	Bill to	Hrs	Rate	Total
------	----------	-------------	--------	------	---------	-----	------	-------

ARR01	Z992	MISC LABOUR CODE	(WARR JGK	W-1021		0.00	140.00	0.00
ARR01	Z992	MISC LABOUR CODE	(WARR JGK	W-1021		0.38	140.00	53.20
ARR01	Z992	MISC LABOUR CODE	(WARR JGK	W-1021		0.12	140.00	16.80
ARR01	WARR	MANUFACTURER WARRANTY	JGK	W-1021		0.50	140.00	70.00
ARR02	Z992	MISC LABOUR CODE	(WARR JGK	W-1021		0.00	140.00	0.00
ARR02	Z992	MISC LABOUR CODE	(WARR JGK	W-1021		0.33	140.00	46.20

Continued on page 3

Work Order : 12066

```

*****
Job#  Lab Code  Description   LABOUR   Mech Bill to    Hrs    Rate    Total
*****
ARR02 Z992      MISC LABOUR CODE (WARR JGK  W-1021    0.17    140.00    23.80
      1 DIAG      DIAGNOSTICS              JGK  I-PD      0.83     70.00    58.10
      1 DIAG      DIAGNOSTICS              JGK  I-PD      0.17     70.00    11.90
ARR03 Z992      MISC LABOUR CODE (WARR JGK  W-1021    0.00    140.00     0.00
ARR03 Z992      MISC LABOUR CODE (WARR JGK  W-1021    0.44    140.00    61.60
ARR03 Z992      MISC LABOUR CODE (WARR JGK  W-1021    0.06    140.00     8.40

```

```

*****
Job #  Excode    Description   EXTRAS      bill to    Qty    Price    Total
*****
      1  SSE      SHOP SUPPLIES - EXTERNAL  I-PD      1.00     0.00     0.00

```

```

*****
                                BILLINGS SUMMARY
Type Bill Id      Parts    Labour    Sublet    Extras      Tax      Total
*****
I      PD          0.00     70.00     0.00     0.00     0.00     70.00
W      1021        33.36    280.00     0.00     0.00     0.00    313.36

      Totals      33.36    350.00     0.00     0.00     0.00    383.36

```

&k2S
&k0S