



# Warranty Claim Form

Date: 7/2/2025

1127 Greenway RV Sales & Service  
8220 State Hwy 13 South  
Wisconsin Rapids, WI 54494  
United States  
Ph. 715-325-5170  
mail@greenwayrv.com

### General Information

573FS3627SAA20575  
Solitude 310GK  
Retail Purchase Date: null  
Work Started: 6/4/2025  
Work Completed: 6/4/2025

Claim Status: Paid  
Dealer Work Order #: 12094B  
Unit Offline Date: 12/11/2024

Claim #: 907294  
Labor: \$168.00  
Parts: \$52.34  
Shipping: \$0.00  
Total: \$220.34

Notes: JPH 6-10-25

### Dealer Information

### Customer Information

1127 Greenway RV Sales & Service  
8220 State Hwy 13 South  
Wisconsin Rapids, WI 54494  
United States

715-325-5170  
mail@greenwayrv.com  
Approved Labor Rate: \$140.00

### Operation Line # 1

*Flat Rate Code:* 430010 Power Center - R&R 12V Fuse      *Fault Code:* Damaged/Maintenance

*Problem:* Something is going on with the electrical.

*Hours:* .2

*Cause:* The ground must have touched metal at some point. Both 40-amp fuses and fuses for water heater were blown.

*Amount:* 28.00

*Remedy:* Removed bad fuses and installed new all is now working as it should. Not sure if it happened from transport or when battery was hooked up on the unit.

*Sublet Repairs:* \$0.00

*Manufacturer #:*

*Model #:*

*Serial #:*

### Operation Line # 2

*Flat Rate Code:* 540003 EPDM Rubber/TPO - Roof Repair      *Fault Code:* Damaged/Maintenance

*Problem:* The roof has sealant gaps in many areas.

*Hours:* 1

*Cause:* Roof sealant gaps.

*Amount:* 140.00

*Remedy:* Roof needs complete reseal. Resealed most of the roof with dicor.

*Sublet Repairs:* \$0.00

*Manufacturer #:*

*Model #:*

*Serial #:*

<u>Part</u>	<u>Description</u>	<u>Return Tag #</u>	<u>Qty</u>	<u>Units</u>	<u>Amount</u>
960204	Miscellaneous Part for claim use only		6	1	0.00
960907	SEAL 1021 WHITE LOW V.O.C. TUBE SELF LEVEL (11 OZ.) 30/CASE	SEALANT 1021 WHITE LOW VOC SELF LEVELING TUBE 30/CASE	6	1	52.34