

FOREST RIVER WARRANTY CLAIM FORM

DEALER ACCOUNT # 0009497
 GREENEWAY INC
 DBA GREENEWAY RV SALES & SERVICE
 8220 STATE HWY 13 SOUTH
 WISCONSIN RAPIDS, WI 54494
 USA

CLAIM STATUS Paid
 CLAIM 2424322
 CLAIM ORIGIN WEB
 ORIGINAL CLAIM ID
 VIN 4X4TFLB2XSD465385
 CHASSIS VIN
 MILEAGE 0
 SITE/WAREHOUSE 010 / 010B
 ITEM # FLT25FKB
 DEALER RO # 12097B
 CLAIM START DATE 09/04/2025
 CLAIM END DATE 09/05/2025

Labor rate: \$140.00
 OWNER INFORMATION

Retail Date of Purchase WARRANTY EXPIRATION DATE

Claim Line Details

Labor

Line# 1	Operation Code 20-89-01-00-000883	Operational Description MaxxAir Garnish Ring - Exterior/Power Roof Vent (MaxxAir)/Replace/No Tread Code
---------	--------------------------------------	--

Complaint, Cause, Correction

Original Note : greeneway@dealer-advisors.com, 2025-09-04 12:40:05 :: Complaint: The vent fan in the bedroom has glue on it on the garnish. Cause: Glue on garnish from manufacturer. Correction: Used quick solve to remove glue. Additional Note : greeneway@dealer-advisors.com, 2025-09-04 12:40:53 :: No repair code.

Model# 1	Dlr Sub Hrs	0.40	Sub Labor Amt	\$56.00
Serial# 1	Appr Hrs	0.20	Appr Labor Amt	\$28.00

Notes

Authorized to clean

Submitted	Labor Amt	\$56.00	Approved	Labor Amt	\$28.00
	Parts & Freight	\$0.00		Parts & Freight	\$0.00
	Total	\$56.00		Total	\$28.00

DEALER _____ DATE _____
 SIGNATURE

I certify that I have performed these repairs consistent with Forest River Policies.

CUSTOMER _____ DATE _____
 SIGNATURE

All repairs described have been inspected and are satisfactory.