

#11299

DAF: Dealer Unit Inspection Form



FOREST RIVER

Forest River, Inc.
2551 Century Drive
Goshen, IN 46528
USA

Short VIN/Unit: PUP104401

Model/Item: PUT403LFT

Dealer: GREENEWAY INC

1. Forest River allows for a secondary inspection, which must take place within **3 business days** from the **delivery date** for warranty consideration.
2. Dealer Unit Inspection Form is to document substantial damage and shortages, not to note minor defects in material or workmanship.
3. If the Dealer is unable to perform this inspection within **3 business days**, the appropriate Warranty Department must be notified via email or phone.
4. The form must be signed and attached to the VIN on Dealer Connect **within 24 hours after the secondary inspection**.
5. Warranty claims must be submitted and resolved no later than **6 months from delivery** for coverage and payment.

Circle Yes or No if item was received, and if applicable:

Keys	☒ Yes	☐ No
BBQ Grill	☒ Yes	☐ No
Power Cord	☒ Yes	☐ No
Warranty Packet	☒ Yes	☐ No
Sink cover	☒ Yes	☐ No
Jack Handles	☒ Yes	☐ No
TV 1	☒ Yes	☐ No
TV 2	☒ Yes	☐ No
Remotes	☒ Yes	☐ No

List Any Miscellaneous Comments Regarding Condition of Unit:

List Any Additional Missing Items:

Suggested areas to inspect:	
Unit Cleanliness ☒	If no, explain:
Condition of Flooring ☒	
Cabinetry Damage ☒	If yes, explain:
Appliance Condition ☒	
Furniture Tears/Stains ☒	If yes, explain:
Frame/Chassis Condition ☒	
Roof Components ☒	
Roof Material ☒	
Awning Fabric ☒	
ODS/DS Walls & Graphics ☒	
Unit Front & Graphics ☒	
Unit Rear & Graphics ☒	
Additional Notations ☒	SLIDE (DRIVER SIDE FRONT) NO OPENING TRIM IS BADLY DAMAGED

Unit/Underside has been washed by the Dealership

Yes

No

Date Washed

Dealer Signature

Date

1-2-2025