



Warranty Claim Form

Date: 9/19/2025

1127 Greenway RV Sales & Service
8220 State Hwy 13 South
Wisconsin Rapids, WI 54494
United States
Ph. 715-325-5170
mail@greenwayrv.com

General Information

573FR4127R9925691
Reflection 362TBS
Retail Purchase Date: 5/30/2025
Work Started: 8/22/2025
Work Completed: 8/22/2025

Claim Status: Paid
Dealer Work Order #: 12151B
Unit Offline Date: 1/11/2024

Claim #: 924512
Labor: \$14.00
Parts: \$1.85
Shipping: \$30.01
Total: \$55.22

Notes:

Dealer Information

1127 Greenway RV Sales & Service
8220 State Hwy 13 South
Wisconsin Rapids, WI 54494
United States

715-325-5170
mail@greenwayrv.com
Approved Labor Rate: \$140.00

Customer Information

HUGH CLARKE
1546 COUNTY ROAD 1400
WILBER, Nebraska 68465
United States
4024167611

Operation Line # 1

Flat Rate Code: 140004 Center Caps - R&R Wheel Center *Fault Code:* Damaged/Maintenance Cap

Problem: Customer states that one of the wheel bearing buddy on the ODS front tire is missing and needs to be replaced.

Hours: .1

Cause: Hub cap fell off.

Amount: 14.00

Remedy: Replace dust cap.

Sublet Repairs: \$0.00

Manufacturer #: 1

Model #: 1

Serial #: 1

<u>Part</u>	<u>Description</u>	<u>Return Tag #</u>	<u>Qty</u>	<u>Units</u>	<u>Amount</u>
140050 TIRE COVER CHROME CENTER SNAP-IN	TIRE COVER CHROME CENTER SNAP-IN		1	1	1.85

Operation Line # 2

Flat Rate Code: 950003 Misc. Charges - Handling Fee

Fault Code: No Problem Identified

Problem: handling for invoice 1444969

Hours: 0

Cause: handling for invoice 1444969

Amount: 0.00

Remedy: handling for invoice 1444969

Sublet Repairs: \$9.36

Manufacturer #:

Model #:

Serial #: