

GREENEWAY, INC.
8220 STATE HWY 13 SOUTH
WISCONSIN RAPIDS WI
US
54494
(715) 325-5170

WORK ORDER # 12155

Date In:	04 JUN 25	Author:	MGRAY
Promised Date:	04 JUL 25	Stock No:	10714
:	:	Year:	2023
Customer Name:	84751 - BERG, KEITH	Manufacturer:	FOREST RIVER
Address:	3810 DOWNING STREET	Brand:	FLAGSTAFF SUPER-LITE T
:	WISCONSIN RAPIDS, WI	Model:	27BHWS
Postal/Zip:	54494	Miles/Hrs:	0
Phone#(res):	715-340-3439	Exterior Color:	:
Phone#(bus):	:	Unit Type:	TT-TRAVEL TRAILER
Cell Phone:	:	License#:	:
Email:	KCBERG08@GMAIL.COM	Tag#:	DB:6/10 apt 7/23
Purchased Date:	24 JUL 24	:	:
Delivery Date:	25 JUL 24	:	:
InService Date:	:	:	:
Serial#:	4X4TFLC20PZ185158	:	:

Job #	Description	JOB INFORMATION	Type	Bill To
WARR	COMPLAINT:	WARRANTY REPAIR 1 - THERE IS SPOTS IN THE FRONT CAP SEALANT THAT HAS SPACES IN IT. CHECK FOR ISSUE AND IF NEEDING RESEAL	W	1021 FORES
	CAUSE:	1001 CUSTOMER REQUESTED. The roof needs a complete re-seal. 10-12 tubes of dicor. The silicone along the ds front screw track has a few small gaps. I cleaned and sealed it. Roof reseal.		
	CORRECTION:	... Resealed complete roof. 13 tube's of white dicor.		
WARR	COMPLAINT:	WARRANTY REPAIR 2 - THERE IS MOISTURE GETTING IN THE SLIDE IN THE BEDROOM WITH THE CLOSET.	W	1021 FORES
	CAUSE:	NPF. The customer had both of the deadbolts locked and didn't leave the keys. The first 10 minutes was spent figuring out the key code. After I got the unit unlocked I checked in and around the slide for water damage and I don't see any. I sprayed the slide with water while it was out, went inside and checked for leaks and everything is dry. I ran the slide in, sprayed and checked it again and still no signs of any water getting in.		
	CORRECTION:	Done. REQUEST .50 HOURS OF LABOR		

Continued on page 2

Work Order : 12155

```
*****
Job # Part No      Description      PARTS      Bill to  Qty      Price      Total
*****
WARR0 677917000333 Dicor 501LSW-1 EPDM Self W-1021      13      8.72      113.36
*****
```

```
*****
Job#  Lab Code  Description      LABOUR      Mech Bill to      Hrs      Rate      Total
*****
ARR01 Z992      MISC LABOUR CODE (WARR JGK W-1021      0.00      140.00      0.00
ARR01 Z992      MISC LABOUR CODE (WARR JGK W-1021      0.00      140.00      0.00
ARR01 Z992      MISC LABOUR CODE (WARR JGK W-1021      0.30      140.00      42.00
ARR01 WARR      MANUFACTURER WARRANTY TD W-1021      2.00      140.00      280.00
ARR02 Z992      MISC LABOUR CODE (WARR JGK W-1021      0.75      140.00      105.00
ARR02 Z992      MISC LABOUR CODE (WARR JGK W-1021      0.00      140.00      0.00
*****
```

```
*****
                                BILLINGS SUMMARY
Type Bill Id      Parts      Labour      Sublet      Extras      Tax      Total
*****
W      1021      113.36      427.00      0.00      0.00      0.00      540.36

      Totals      113.36      427.00      0.00      0.00      0.00      540.36
*****
```

&k2S
&k0S