



Warranty Claim Form

Date: 6/19/2025

1127 Greenway RV Sales & Service
8220 State Hwy 13 South
Wisconsin Rapids, WI 54494
United States
Ph. 715-325-5170
mail@greenwayrv.com

General Information

573FR3322T3353771
Reflection 27BH
Retail Purchase Date: 6/9/2025
Work Started: 6/9/2025
Work Completed: 6/9/2025

Claim Status: Paid
Dealer Work Order #: 12160
Unit Offline Date: 5/21/2025

Claim #: 904326
Labor: \$56.00
Parts: \$0.00
Shipping: \$0.00
Total: \$56.00

Notes:

Dealer Information

Customer Information

1127 Greenway RV Sales & Service
8220 State Hwy 13 South
Wisconsin Rapids, WI 54494
United States

715-325-5170
mail@greenwayrv.com
Approved Labor Rate: \$140.00

Operation Line # 1

Flat Rate Code: 710018 Ducting - Repair Plenum - Furnace *Fault Code:* Improper Installation/Build Discharge

Problem: Furnace flow.

Hours: .4

Cause: While doing full prep, noticed furnace exhaust flange is protruding in a weird way. Requires adjustment of internal furnace components.

Amount: 56.00

Remedy: Have to remove the furnace exhaust flange, cut off excessive exhaust pipe by 3/8", deburr pipe, reassemble, remount exhaust flange and test.

Sublet Repairs: \$0.00

Manufacturer #:

Model #:

Serial #: