



Warranty Claim Form

Date: 9/3/2025

1127 Greenway RV Sales & Service
8220 State Hwy 13 South
Wisconsin Rapids, WI 54494
United States
Ph. 715-325-5170
mail@greenwayrv.com

General Information

573FR4022S9929980
Reflection 360FLS
Retail Purchase Date: 7/8/2025
Work Started: 8/14/2025
Work Completed: 8/14/2025

Claim Status: Paid
Dealer Work Order #: 12172
Unit Offline Date: 5/1/2025

Claim #: 922889
Labor: \$56.00
Parts: \$1.90
Shipping: \$0.73
Total: \$58.63

Notes: jph 7-14-25 420050 DENIED, LOT DAMAGE.

Dealer Information

1127 Greenway RV Sales & Service
8220 State Hwy 13 South
Wisconsin Rapids, WI 54494
United States

715-325-5170
mail@greenwayrv.com
Approved Labor Rate: \$140.00

Customer Information

DANNY PRICE
8201 MORGAN LAKE RD
FENCE, Wisconsin 54120
United States
2627074383

Operation Line # 1

Flat Rate Code: 420004 Lights (Exterior) - R&R Tail Light *Fault Code:* Damaged/Maintenance

Problem: Tail light lens cracked.

Hours: .2

Cause: Tail light lens cracked.

Amount: 28.00

Remedy: Need new lens for tail light.

Sublet Repairs: \$0.00

Manufacturer #:

Model #:

Serial #:

<u>Part</u>	<u>Description</u>	<u>Return Tag #</u>	<u>Qty</u>	<u>Units</u>	<u>Amount</u>
420064 TAIL LIGHT REFLECT RING FOR STL 78RB RED	TAIL LIGHT REFLECT RING FOR STL 78RB RED		1	1	1.90

Operation Line # 2

Flat Rate Code: 160039 Electric Leveling - Electric Leveling - *Fault Code:* Damaged/Maintenance
Calibrate Control Pad

Problem: Need to calibrate auto leveling system.

Hours: .2

Cause: Not operating correctly.

Amount: 28.00

Remedy: Leveling system recalibrate. Tested good.

Sublet Repairs: \$0.00

Manufacturer #:

Model #:

Serial #: