

GREENEWAY, INC.
8220 STATE HWY 13 SOUTH
WISCONSIN RAPIDS WI
US
54494
(715) 325-5170

WORK ORDER # 12197

Date In:	10 JUN 25	Author:	MGRAY
Promised Date:	30 JUN 25	Stock No:	11082
:	:	Year:	2022
Customer Name:	1021 - FOREST RIVER	Manufacturer:	FOREST RIVER
Address:	21815 NETWORK PLACE	Brand:	PUMA TT
:	CHICAGO, IL	Model:	25BHFQ
Postal/Zip:	60673-1218	Miles/Hrs:	0
Phone#(res):	219-534-3167	Exterior Color:	:
Phone#(bus):	219-534-3167	Unit Type:	TT-TRAVEL TRAILER
Cell Phone:	:	License#:	:
Email:	NONE	Tag#:	:
Purchased Date:	20 JUN 24	:	:
Delivery Date:	28 JUN 24	:	:
InService Date:	:	:	:
Serial#:	5ZT2PUPB7N4016293	:	:

Job #	Description	JOB INFORMATION	Type	Bill To
WARR	COMPLAINT:	WARRANTY REPAIR 1 - REGULATOR SWITCH IS BROKEN AND HOSE IS LEAKING,	W	1021 FORES
	CAUSE:	Request test regulator. Removed fitting from regulator and put in a plug. Seal on pigtail is leaking, regulator selector switch not staying connected. need regulator replacement		
WARR	COMPLAINT:	WARRANTY REPAIR 2 - COUCH THAT HAD BEEN REPLACED ON PREVIOUS WARRANTY APPROVAL 2172933, IS BENT IN CENTER AGAIN. CMR WOULD LIKE TO HAVE REPLACED AGAIN UNDER WARRANTY.	W	1021 FORES
	CAUSE:	center on couch is bent. would recommend replacement.		

Job#	Lab Code	Description	LABOUR	Mech	Bill to	Hrs	Rate	Total
ARR01	Z992	MISC LABOUR CODE (WARR	RW	W-1021		0.50	140.00	70.00
ARR02	Z992	MISC LABOUR CODE (WARR		W-1021		0.00	140.00	0.00

BILLINGS SUMMARY							
Type	Bill Id	Parts	Labour	Sublet	Extras	Tax	Total
W	1021	0.00	70.00	0.00	0.00	0.00	70.00

Continued on page 2

Work Order : 12197

BILLINGS SUMMARY

Type Bill Id	Parts	Labour	Sublet	Extras	Tax	Total

Totals	0.00	70.00	0.00	0.00	0.00	70.00

&k2S
&k0S