

GREENEWAY, INC.
8220 STATE HWY 13 SOUTH
WISCONSIN RAPIDS WI
US
54494
(715) 325-5170

WORK ORDER # 12247B

Date In: 20 JUN 25 Author: KOTT
Promised Date: 25 DEC 25 Stock No: 11443
: Year: 2026
Customer Name: 116234 - JOHNSON, JAME Manufacturer: GRAND DESIGN
Address: 2525 S MEADOWVIEW LANE Brand: REFLECTION 150 SERIES
: APPLETON, WI Model: 260RD
Postal/Zip: 54915 Miles/Hrs: 0
Phone#(res): 920-585-4083 Exterior Color:
Phone#(bus): Unit Type: FW-FIFTH WHEEL
Cell Phone: License#:
Email: JLJOHN4@SBCGLOBAL.NET; Tag#: DB: 6/20
Purchased Date: 11 JUN 25 :
Delivery Date: 25 DEC 25 :
InService Date: :
Serial#: 573FR3124T3353872 :

Job # Description JOB INFORMATION Type Bill To

7 COMPLAINT: WHEN UNIT WAS DROPPED OFF FOUND THAT THE W 1020 GRAND
LINO IN THE BEDROOM ON THE RIGHT SIDE OF
THE BED IF YOU ARE AT THE FOOT IS NOT
TUCKED UNDER THE TRIM PIECE
CAUSE: WILL NEED TO REMOVE THE BLACK TRIM
THING, TUCK THE LINO DOWN UNDER IT, THEN
REINSTALL. WILL ALSO NEED TO REMOVE THE
BATTEN PIECE A THE TOP OF THE LINO
PIECE, LAY THE LINO DOWN, THEN REINSTALL
THE LINO-
CORRECTION: REQUEST 2 HOURS OF LABOR
8 COMPLAINT: AT THE TIME OF DROP OFF FOUND THAT THERE W 1020 GRAND
IS A DENT IN THE PROPANE COMPARTMENT
DOOR-
CAUSE: DENT IN THE COMPARTMENT DOOR- WILL NEED
TO BE REPLACED
CORRECTION: R&R COMPARTMENT DOOR- REQUEST 1.50
HOURS OF LABOR
1 COMPLAINT: AT THE TIME OF THE DROP OFF FOUND THAT W 1020 GRAND
THE WEDGE ON THE KING PIN IS DAMAGED- IT
IS BENT- WILL NEED TO REPLACED
CAUSE: WILL NEED TO REPLACE THE WEDGE-
CORRECTION: REQUEST .20 HOURS OF LABOR

Continued on page 2

Work Order : 12247B

BILLINGS SUMMARY

Type Bill Id	Parts	Labour	Sublet	Extras	Tax	Total
Totals	0.00	0.00	0.00	0.00	0.00	0.00

&k2S
&k0S