



Warranty Claim Form

Date: 3/11/2026

1127 Greenway RV Sales & Service
8220 State Hwy 13 South
Wisconsin Rapids, WI 54494
United States
Ph. 715-325-5170
mail@greenwayrv.com

General Information

573TE2920T6655574
Imagine 2470BH
Retail Purchase Date: null
Work Started: 11/18/2025
Work Completed: 2/27/2026

Claim Status: Paid
Dealer Work Order #: 12324B
Unit Offline Date: 6/25/2025

Claim #: 970846
Labor: \$70.00
Parts: \$83.37
Shipping: \$15.66
Total: \$178.65

Notes: Sg 1/27/25 *Please hold all parts for a minimum of 30 days after the claim is paid*

Dealer Information

Customer Information

1127 Greenway RV Sales & Service
8220 State Hwy 13 South
Wisconsin Rapids, WI 54494
United States

715-325-5170
mail@greenwayrv.com
Approved Labor Rate: \$140.00

Operation Line # 1

Flat Rate Code: 660001 Cabinet Doors - R&R Door

Fault Code: Damaged/Maintenance

Problem: Glass in ODS over head cabinet in bedroom has a chip in it.

Hours: .3

Cause: Chipped glass.

Amount: 42.00

Remedy: R&R cabinet door with glass. 30 1/2 wide x 28 1/2 tall smoked glass cabinet door.

Sublet Repairs: \$0.00

Manufacturer #:

Model #:

Serial #:

<u>Part</u>	<u>Description</u>	<u>Return Tag #</u>	<u>Qty</u>	<u>Units</u>	<u>Amount</u>
664825 DOOR CABINET 15MM X 30 1/2 X 11 1/4 NATURAL TEAK W/GLASS	DOOR CABINET 15MM X 30 1/2 X 11 1/4 NATURAL TEAK W/GLASS		1	1	83.37

Operation Line # 2

Flat Rate Code: 590026 Range Hood Vent - R&R Vent

Fault Code: Improper Installation/Build

Problem: The vent fan above the stove is rubbing.

Hours: .2

Cause: Fan blades rubbing on metal screen.

Amount: 28.00

Remedy: Adjust the fan so it will not hit the grates. No repair/adjust code available.

Sublet Repairs: \$0.00

Manufacturer #:

Model #:

Serial #:

Operation Line # 3

Flat Rate Code: 950003 Misc Charges - Packaging/Handling *Fault Code:* No Problem Identified
Fee

Problem: Invoice 1541684

Hours: 0

Cause: Invoice 1541684

Amount: 0.00

Remedy: Invoice 1541684

Sublet Repairs: \$9.62

Manufacturer #:

Model #:

Serial #: