



Warranty Claim Form

Date: 12/18/2025

1127 Greenway RV Sales & Service
8220 State Hwy 13 South
Wisconsin Rapids, WI 54494
United States
Ph. 715-325-5170
mail@greenwayrv.com

General Information

573FR3722T9930449
Reflection 337RLS
Retail Purchase Date: null
Work Started: 12/4/2025
Work Completed: 12/4/2025

Claim Status: Paid
Dealer Work Order #: 12419B
Unit Offline Date: 6/25/2025

Claim #: 952596
Labor: \$126.00
Parts: \$0.00
Shipping: \$0.00
Total: \$126.00

Notes: AB 12/9 *Please hold all parts for a minimum of 30 days after the claim is paid* 960244 - Noted for now.

Dealer Information

Customer Information

1127 Greenway RV Sales & Service
8220 State Hwy 13 South
Wisconsin Rapids, WI 54494
United States

715-325-5170
mail@greenwayrv.com
Approved Labor Rate: \$140.00

Operation Line # 1

Flat Rate Code: 650015 Closet/Pantry Cabinets - Repair *Fault Code:* Improper Installation/Build Cabinet

Problem: The DS of the wardrobe closet in bedroom, the bottom of the stile has a large gouge out of it.

Hours: .3

Cause: Gouged stile on wardrobe closet.

Amount: 42.00

Remedy: Used putty to fill the gouge.

Sublet Repairs: \$0.00

Manufacturer #:

Model #:

Serial #:

Operation Line # 2

Flat Rate Code: 610005 Vinyl Board - Putty T-Nail Holes (per *Fault Code:* Improper Installation/Build panel)

Problem: The wall across from bathroom has a nail that is very visible and not filled.

Hours: .1

Cause: Nail protruding.

Amount: 14.00

Remedy: Set the nail and filled it with putty - no repair code.

Sublet Repairs: \$0.00

Manufacturer #:

Model #:

Serial #:

Operation Line # 3

Flat Rate Code: 670018 Kitchen - Countertop Repair

Fault Code: Improper Installation/Build

Problem: Edge of the counter tops have black marks on them, do not come off with just a wipe.

Hours: .5

Cause: Black scuffs on edge of countertops.

Amount: 70.00

Remedy: Took a bit of scouring liquid and removed the marks by buffing them out with a cloth.

Sublet Repairs: \$0.00

Manufacturer #:

Model #:

Serial #: