

FOREST RIVER WARRANTY CLAIM FORM

DEALER ACCOUNT #	0009497	CLAIM STATUS	Paid
GREENEWAY INC		CLAIM	2542734
DBA GREENEWAY RV SALES & SERVICE		CLAIM ORIGIN	WEB
8220 STATE HWY 13 SOUTH		ORIGINAL CLAIM ID	
WISCONSIN RAPIDS, WI 54494		VIN	4X4TFLF28TZ198830
USA		CHASSIS VIN	
		MILEAGE	0
Labor rate:	\$140.00	SITE/WAREHOUSE	010 / 010D
OWNER INFORMATION		ITEM #	FLT26SFK
THOMAS WEBER		DEALER RO #	12632B
324 NEW MARKET CT		CLAIM START DATE	01/06/2026
Nekoosa, WI 54457		CLAIM END DATE	03/05/2026
USA			
Retail Date of Purchase	09/26/2025	WARRANTY EXPIRATION DATE	09/26/2026

Claim Line Details

Labor

Line# 1

Operation Code

40-112-01-11-001353

Operational Description

Tank Sensor - Probe Pods, each - Electrical/Monitor Panel/Replace/Electrical

Complaint, Cause, Correction

Original Note : greeneway@dealer-advisors.com, 2026-01-06 14:40:50 :: Complaint: Two different holding tanks are not reading accurately. Cause: The probes that are currently intalled on the unit are installed too high and are caught in an air bubble. Correction: We will need to drop the underbelly, remove the tanks, install new probes on both tanks, reinstall the tanks, and put the underbelly back up. Additional Note : greeneway@dealer-advisors.com, 2026-01-06 14:41:28 :: No repair code.

Model#

Dlr Sub Hrs

10.00

Sub Labor Amt

\$1,400.00

Serial#

Appr Hrs

20.00

Appr Labor Amt

\$2,800.00

Notes

hello, the authorization to replace the probes on both tanks is pending photos of both tanks including any vendor stamps/logos as well as a photo of all probes before and after replacement. Failure to submit these photos at the time of repair is subject to result in denial of the claim. Thank you!

After talking to the dealership managment and Forestriver upper managment we will one time good will the excessive time of 20 hrs for this claim .

Part

Line# 1	Item #	Description		
	F100409815	MONITOR PANEL PART - PFL: DIMMING CONTROL BOARD, UNITY X270D - V# 2023018428 X 2023018428 (9A-SOP)		
	Model #	Serial #	Part tag	0000404875
	Sub Qty	1.00	Sub Dlr Price	\$404.57
	Appr Qty	1.00	Sub Freight	\$23.91
		Appr Dlr Price	Appr Freight	\$23.91
	Notes			
Line# 2	Item #	Description		
	USERPART	shop supplies: tank holding prove well nut		
	Model #	Serial #	Part tag	0000404874
	Sub Qty	2.00	Sub Dlr Price	\$2.78
	Appr Qty	2.00	Sub Freight	\$0.00
		Appr Dlr Price	Appr Freight	\$0.00
	Notes			

Submitted	Labor Amt	\$1,400.00	Approved	Labor Amt	\$2,800.00
	Parts & Freight	\$431.26		Parts & Freight	\$431.26

Total \$1,831.26

Total \$3,231.26

DEALER

SIGNATURE

DATE

I certify that I have performed these repairs consistent with Forest River Policies.

CUSTOMER

SIGNATURE

DATE

All repairs described have been inspected and are satisfactory.