

FOREST RIVER WARRANTY CLAIM FORM

DEALER ACCOUNT # 0009497
GREENEWAY INC
DBA GREENEWAY RV SALES & SERVICE
8220 STATE HWY 13 SOUTH
WISCONSIN RAPIDS, WI 54494
USA

CLAIM STATUS Paid
CLAIM 2443904
CLAIM ORIGIN WEB
ORIGINAL CLAIM ID
VIN 5ZT2PUEC0T4025653
CHASSIS VIN
MILEAGE 0
SITE/WAREHOUSE 425 / 425
ITEM # PUT16BHCE-1
DEALER RO # 12663B
CLAIM START DATE 09/22/2025
CLAIM END DATE 02/18/2026

Labor rate: \$140.00
OWNER INFORMATION

Retail Date of Purchase

WARRANTY EXPIRATION DATE

Claim Line Details

Labor

Line# 1	Operation Code	Operational Description
	20-43-01-00-000589	Die Cut, Stripe, Decal, Graphic - Exterior/Exterior Miscellaneous/Replace/No Tread Code

Complaint, Cause, Correction

Original Note : greeneway@dealer-advisors.com, 2025-09-22 16:54:55 :: Complaint: The rear PUMA decal is bubbling. Cause: The rear puma decal is bubbling. Correction: Tried to flatten them but they keep coming back, need to replace decal.

Model#	Dlr Sub Hrs	0.50	Sub Labor Amt	\$70.00
Serial#	Appr Hrs	0.50	Appr Labor Amt	\$70.00

Notes

these decals look repairable , how are you guys trying to repair these ??
With a heat gun and/or small needle poke a hole in it to get the ait out to attempt to get them flat.
Thank you.
flat rate to repair

Submitted	Labor Amt	\$70.00	Approved	Labor Amt	\$70.00
	Parts & Freight	\$0.00		Parts & Freight	\$0.00
	Total	\$70.00		Total	\$70.00

DEALER _____ DATE _____
SIGNATURE

I certify that I have performed these repairs consistent with Forest River Policies.

CUSTOMER _____ DATE _____
SIGNATURE

All repairs described have been inspected and are satisfactory.