

GREENEWAY, INC.
8220 STATE HWY 13 SOUTH
WISCONSIN RAPIDS WI
US
54494
(715) 325-5170

WORK ORDER # 12710B

Date In:	16 SEP 25	Author:	KOTT
Promised Date:	25 DEC 25	Stock No:	11500
:	:	Year:	2026
Customer Name:	1020 - GRAND DESIGN	Manufacturer:	GRAND DESIGN
Address:	11333 COUNTY RD 2	Brand:	TRANSCEND
:	MIDDLEBURY, IN	Model:	315RKT
Postal/Zip:	46540	Miles/Hrs:	0
Phone#(res):	888-825-2820	Exterior Color:	:
Phone#(bus):	:	Unit Type:	TT-TRAVEL TRAILER
Cell Phone:	:	License#:	:
Email:	NONE	Tag#:	DB: 9/19
Purchased Date:	09 SEP 25	:	:
Delivery Date:	18 SEP 25	:	:
InService Date:	:	:	:
Serial#:	573TT3721T8840719	:	:

```
*****
Job #   Description                JOB INFORMATION                Type Bill To
*****
3       COMPLAINT:  FIX TABLE (WOBBLY)                        W      1020    GRAND
      CAUSE:        Loose knobs
      CORRECTION:    Tightened the knobs and tightened the
                    cinch clamp  REQUEST .10 HOURS OF LABOR
                    approved .2 labor
WARR    COMPLAINT:  WARRANTY REPAIR 1 - shower base is not    W      1020    GRAND
                    sealed properly it allows water to seep
                    out of the side of the shower base
      CAUSE:        Improper sealing of shower base from mfg
      CORRECTION:    Used air nozzle to get all water away
                    from where I need to seal then used
                    clear sealant to seal the base no longer
                    allowing water to get through  REQUEST
                    .50 HOURS OF LABOR  approved .2 labor
WARR    COMPLAINT:  WARRANTY REPAIR 2 - bathroom door is      W      1020    GRAND
                    touching at the top but see through the
                    bottom
      CAUSE:        Mfg installed incorrectly
      CORRECTION:    Removed the header and adjusted the
                    rollers it now is touching at top and
                    bottom the same also when reinstalling
                    header put screw in straight so door
                    does not rub on header  REQUEST .20
                    HOURS OF LABOR  approved .2 labor
WARR    COMPLAINT:  WARRANTY REPAIR 3 -edge of bedroom door  W      1020    GRAND
                    is scraped
      CAUSE:        Mfg- SCRATCHED
      CORRECTION:    Used wood crayon to cover  REQUEST .10
```

Continued on page 2

Work Order : 12710B

```

*****
Job #   Description           JOB INFORMATION           Type Bill To
*****
WARR    COMPLAINT:  HOURS OF LABOR approved .2 labor
              WARRANTY REPAIR 4 - top edge of drawer  W    1020    GRAND
              in the bedroom is scraped
              CAUSE:  Scrape
              CORRECTION: Used putty to cover the scrape REQUEST
              .30 HOURS OF LABOR approved .20 labor
WARR    COMPLAINT:  WARRANTY REPAIR 5 - scratches and  W    1020    GRAND
              scrapes throughout the unit
              CAUSE:  Scrapes chips in wood from mfg
              CORRECTION: Used putty and wood crayon to fill or
              cover scrapes ,chips holes REQUEST .30
              HOURS OF LABOR approved .30 labor
WARR    COMPLAINT:  WARRANTY REPAIR 6 - roof has 3 bubbles  W    1020    GRAND
              that need to be sealed
              CAUSE:  Bubbles in dicor
              CORRECTION: Cleaned areas then filled with dicor and
              covered with dicor REQUEST .30 HOURS OF
              LABOR approved .2 labor
WARR    COMPLAINT:  WARRANTY REPAIR 7 - the shower surround W    1020    GRAND
              has 2 cracks in the walls
              CAUSE:  The mfg used a cracked surround and
              tried to cover them with glue or sealant
              . Please order new shower surround pics
              taken of tag and cracks
              CORRECTION: ..... REQUEST 3 HOURS OF LABOR

```

```

*****
Job#  Lab Code  Description  LABOUR  Mech Bill to  Hrs  Rate  Total
*****
3 WARR  MANUFACTURER WARRANTY HOD W-1020  0.20  140.00  28.00
ARR01 Z992  MISC LABOUR CODE (WARR HOD W-1020  0.20  140.00  28.00
ARR02 Z992  MISC LABOUR CODE (WARR HOD W-1020  0.20  140.00  28.00
ARR03 Z992  MISC LABOUR CODE (WARR HOD W-1020  0.20  140.00  28.00
ARR04 Z992  MISC LABOUR CODE (WARR HOD W-1020  0.20  140.00  28.00
ARR05 Z992  MISC LABOUR CODE (WARR HOD W-1020  0.30  140.00  42.00
ARR06 Z992  MISC LABOUR CODE (WARR HOD W-1020  0.20  140.00  28.00
ARR07 Z992  MISC LABOUR CODE (WARR HOD W-1020  0.05  140.00  7.00

```

```

*****
Job #  Excode  Description  EXTRAS  bill to  Qty  Price  Total
*****
ARR01 SSE  SHOP SUPPLIES - EXTERNAL W-1020  1.00  0.00  0.00

```

```

*****
Type Bill Id  Parts  Labour  Sublet  Extras  Tax  Total
*****
W 1020  0.00  217.00  0.00  0.00  0.00  217.00

```

Continued on page 3

Work Order : 12710B

BILLINGS SUMMARY

Type Bill Id	Parts	Labour	Sublet	Extras	Tax	Total

Totals	0.00	217.00	0.00	0.00	0.00	217.00

&k2S
&k0S