



Warranty Claim Form

Date: 2/26/2026

1127 Greenway RV Sales & Service
8220 State Hwy 13 South
Wisconsin Rapids, WI 54494
United States
Ph. 715-325-5170
mail@greenwayrv.com

General Information

573TT3223T8841880

Transcend 27DBX

Retail Purchase Date: null

Work Started: 9/29/2025

Work Completed: 2/18/2026

Claim Status: Paid

Dealer Work Order #: 12796B

Unit Offline Date: 9/5/2025

Claim #: 968103

Labor: \$84.00

Parts: \$36.15

Shipping: \$15.61

Total: \$139.93

Notes: RJ 10/06/25 *Please hold all parts for a minimum of 30 days after claim is paid*

Dealer Information

1127 Greenway RV Sales & Service
8220 State Hwy 13 South
Wisconsin Rapids, WI 54494
United States

715-325-5170
mail@greenwayrv.com
Approved Labor Rate: \$140.00

Customer Information

Operation Line # 1

Flat Rate Code: 610011 Moldings/Trims - Repair (per Piece) Fault Code: Improper Installation/Build

Problem: Loose trim in the bathroom.

Hours: .3

Cause: loose trim from manufacturer.

Amount: 42.00

Remedy: Pin nailed the trim in a few spots.

Sublet Repairs: \$0.00

Manufacturer #:

Model #:

Serial #:

Operation Line # 2

Flat Rate Code: 660001 Cabinet Doors - R&R Door

Fault Code: Improper Installation/Build

Problem: Scratch in the bathroom mirror

Hours: .3

Cause: Mirror cabinet in bathroom has a deep scratch in the glass.

Amount: 42.00

Remedy: Replace cabinet door with mirror in bathroom. *There are no tags on the door, so I am unsure on brand.

Sublet Repairs: \$0.00

Manufacturer #:

Model #:

Serial #:

<u>Part</u>	<u>Description</u>	<u>Return Tag #</u>	<u>Qty</u>	<u>Units</u>	<u>Amount</u>
664621 DOOR CABINET 12 X 24 ANNA MAPLE BVLD W/ MIRROR	DOOR CABINET 12 X 24 ANNA MAPLE BVLD W/ MIRROR		1	1	36.15

Operation Line # 3

Flat Rate Code: 950003 Misc Charges - Packaging/Handling *Fault Code:* No Problem Identified
Fee

Problem: Invoice 1532927

Hours: 0

Cause: Invoice 1532927

Amount: 0.00

Remedy: Invoice 1532927

Sublet Repairs: \$4.17

Manufacturer #:

Model #:

Serial #: