

GREENEWAY, INC.
8220 STATE HWY 13 SOUTH
WISCONSIN RAPIDS WI
US
54494
(715) 325-5170

WORK ORDER # 12799

Date In: 23 SEP 25 Author: MGRAY
Promised Date: 31 MAY 26 Stock No: 11107
: Year: 2024
Customer Name: 1021 - FOREST RIVER Manufacturer: FOREST RIVER
Address: 21815 NETWORK PLACE Brand: PUMA TT
: CHICAGO, IL Model: 25BHS
Postal/Zip: 60673-1218 Miles/Hrs: 0
Phone#(res): 219-534-3167 Exterior Color:
Phone#(bus): 219-534-3167 Unit Type: TT-TRAVEL TRAILER
Cell Phone: License#:
Email: NONE Tag#: WS COMP
Purchased Date: 24 MAY 25 :
Delivery Date: 05 JUN 25 :
InService Date: :
Serial#: 5ZT2PUPB6R4020714 :

Job #	Description	JOB INFORMATION	Type	Bill To
SS	SEASONAL STORAGE		E	17725 STEIN
WS	COMPLAINT: WINTERIZE WATER SYSTEM & TRAPS -SELF		E	17725 STEIN
	CONTAINED - TOWABLE			
	CAUSE: Needed to be winterized			
	CORRECTION: Been winterized			
1	COMPLAINT: THE PLUG IN THE BOTTOM BUNK FOR THE PHONE CHARGER HAS A LIGHT ON IT BUT IT DOES NOT CHARGE ANYTHING		W	1021 FORES
	CAUSE: pics taken i also checked voltage going to usb port is 13.62 but nothing coming out			
	CORRECTION: will need a new usb charging port ... lower bunk area REQUEST .75			
2	COMPLAINT: THE WHITE STUFF ON THE BACK OF THE BLIND W ON THE TOP BUNK IS STARTING TO COME OFF		W	1021 FORES
	CAUSE: pics and measurements taken of shade has a hole in it			
	CORRECTION: will need a new shade above the bunk beds.....			
3	COMPLAINT: CUSTOMER STATES THAT THE AWNING ROLLS UP W REALLY WEIRD- IT ALMOST SEEMS LIKE THE HARDWARE ON THE LEFT SIDE IF YOU ARE LOOKING AT THE SIDE OF THE UNIT DOES NOT COME IN ALL THE WAY FLUSH		W	1021 FORES
	CAUSE: pics taken og awning tags what I found was the awning arm on off motor side was catching at the top			
	CORRECTION: so i remove the set screw in awning			

Continued on page 2

Work Order : 12799

 Job # Description JOB INFORMATION Type Bill To

 rail and adjustments made to fabric so
 the arm will retract all the way in
 after adjustments the awning seems to be
 closing correctly

Job #	Part No	Description	PARTS	Bill to	Qty	Price	Total
WS	071247312003	-50 ANTIFREEZE/	1 GALLON	E-17725	0	9.62	0.00
1	EST	F100477100 -	RECEPTACLE,	W-1021	0	32.50	0.00

Job#	Lab Code	Description	LABOUR	Mech	Bill to	Hrs	Rate	Total
WS	W495	WINTERIZE RV	(WATER SY JL		E-17725	0.40	130.00	52.00
WS	W495	WINTERIZE RV	(WATER SY JL		E-17725	0.30	130.00	39.00
1	WARR	MANUFACTURER	WARRANTY	JS	W-1021	0.50	140.00	70.00
2	WARR	MANUFACTURER	WARRANTY	JS	W-1021	0.50	140.00	70.00
3	WARR	MANUFACTURER	WARRANTY	JS	W-1021	0.50	140.00	70.00

Job #	Excode	Description	EXTRAS	bill to	Qty	Price	Total
SS	SS	SEASONAL STORAGE		E-17725	0.00	0.00	0.00
SS	SSE	SHOP SUPPLIES -	EXTERNAL	E-17725	1.00	6.83	6.83
SS	J-ADJ	QUOTE ADJUSTMENT		E-17725	1.00	200.17	200.17
WS	J-ADJ	QUOTE ADJUSTMENT		E-17725	1.00	14.00	14.00

 BILLINGS SUMMARY

Type	Bill Id	Parts	Labour	Sublet	Extras	Tax	Total
E	17725	0.00	91.00	0.00	221.00	17.19	329.19
W	1021	0.00	210.00	0.00	0.00	0.00	210.00
	Totals	0.00	301.00	0.00	221.00	17.19	539.19

&k2S
 &k0S