

GREENEWAY, INC.
8220 STATE HWY 13 SOUTH
WISCONSIN RAPIDS WI
US
54494
(715) 325-5170

WORK ORDER # 12837B

| | | | |
|-----------------|---------------------|-----------------|----------------------|
| Date In: | 03 NOV 25 | Author: | MGRAY |
| Promised Date: | 31 DEC 25 | Stock No: | 11480 |
| : | : | Year: | 2026 |
| Customer Name: | 1021 - FOREST RIVER | Manufacturer: | FOREST RIVER |
| Address: | 21815 NETWORK PLACE | Brand: | PUMA CAMPING EDITION |
| : | CHICAGO, IL | Model: | 16BHCE |
| Postal/Zip: | 60673-1218 | Miles/Hrs: | 0 |
| Phone#(res): | 219-534-3167 | Exterior Color: | : |
| Phone#(bus): | 219-534-3167 | Unit Type: | TT-TRAVEL TRAILER |
| Cell Phone: | : | License#: | : |
| Email: | NONE | Tag#: | : |
| Purchased Date: | : | : | : |
| Delivery Date: | : | : | : |
| InService Date: | : | : | : |
| Serial#: | 5ZT2PUEC7T4025651 | : | : |

Job # Description JOB INFORMATION Type Bill To

WARR COMPLAINT: WARRANTY REPAIR 1 - The seal on the ods W 1021 FORES
front window is not peeling off on the
bottom and is no longer sticky.
CAUSE: The bulb seal on the front ods window
was coming off, i put a whole new seal
around the window. Forgot to clock out
only took 30 min
CORRECTION: Done

Job # Part No Description PARTS Bill to Qty Price Total

WARR0 82200251 SEAL BAGGAGE DOOR 1/4 X 1/2 W-1021 8 1.77 14.16

Job# Lab Code Description LABOUR Mech Bill to Hrs Rate Total

ARR01 Z992 MISC LABOUR CODE (WARR EG W-1021 0.00 140.00 0.00
ARR01 Z992 MISC LABOUR CODE (WARR EG W-1021 0.50 140.00 70.00

Job # Excode Description EXTRAS bill to Qty Price Total

ARR01 SSE SHOP SUPPLIES - EXTERNAL W-1021 1.00 0.00 0.00

Work Order : 12837B

BILLINGS SUMMARY

| Type | Bill Id | Parts | Labour | Sublet | Extras | Tax | Total |
|------|---------|-------|--------|--------|--------|------|-------|
| W | 1021 | 14.16 | 70.00 | 0.00 | 0.00 | 0.00 | 84.16 |
| | Totals | 14.16 | 70.00 | 0.00 | 0.00 | 0.00 | 84.16 |

&k2S
&k0S