

GREENEWAY, INC.
8220 STATE HWY 13 SOUTH
WISCONSIN RAPIDS WI
US
54494
(715) 325-5170

WORK ORDER # 12845

Date In: 27 SEP 25 Author: MGRAY
Promised Date: 07 OCT 25 Stock No: 11500
: Year: 2026
Customer Name: 17843 - CAMPBELL, KERR Manufacturer: GRAND DESIGN
Address: 1962 19TH CREEK Brand: TRANSCEND
: ARKDALE, WI Model: 315RKT
Postal/Zip: 54613 Miles/Hrs:
Phone#(res): 6085166746 Exterior Color:
Phone#(bus): Unit Type: TT-TRAVEL TRAILER
Cell Phone: License#:
Email: KERRI@KERRICAMPBELL.NE Tag#:
Purchased Date: 09 SEP 25 :
Delivery Date: 18 SEP 25 :
InService Date: :
Serial#: 573TT3721T8840719 :

Job # Description JOB INFORMATION Type Bill To

WARR COMPLAINT: WARRANTY REPAIR 1 - stereo doesn't W 1020 GRAND
adjust quiet enough with either my phone
or the volume now
CAUSE: NPF. I hooked my phone up to the radio
and turned the volume up and down and it
turns off from my phone and the radio.
CORRECTION: Done. REQ: .20 HRS
WARR COMPLAINT: WARRANTY REPAIR 2 - dead bolt isn't W 1020 GRAND
aligned and doesn't work.
CAUSE: The door catch was upside down. I
installed it the correct way and the
deadbolt catches.
CORRECTION: Done REQ: .20
WARR COMPLAINT: WARRANTY REPAIR 3 - shower door leaks W 1020 GRAND
where it retracts into
CAUSE: The manufacturer didn't seal around the
shower properly. I poured water down
the edge and it started leaking right
away. I sealed around the problem area
and I let it dry. After the sealant
dried I poured water on it and the leak
stopped.
CORRECTION: Done. REQ: .40
WARR COMPLAINT: WARRANTY REPAIR 4 - glue/caulk on W 1020 GRAND
multiple surfaces on interior
living/kitchen area - needs to be
cleaned off.
CAUSE: There are multiple surfaces to a camper.

Continued on page 2

Work Order : 12845

Job #	Description	JOB INFORMATION	Type	Bill To
-------	-------------	-----------------	------	---------

I need to know where. Is it inside, outside, DS, ODS, top or bottom? I cleaned up some silicone i found on the outside and we received more information from the customer and he states its on the inside by the booth and kitchen area. I found some spots that had access putty that i cleaned off with a rag.

CORRECTION: Done. REQ: .50

WARR	COMPLAINT:	WARRANTY REPAIR 5 - the floor is causing W	1020	GRAND
		a bad squeak between the bathroom and the bedroom.		

CAUSE: The noise is coming from the ceiling. The ceiling panel or something in the ceiling by the bedroom door is flexing. I can push on the paneling and it makes the same noise as when your walking down the hallway.

CORRECTION: Will need to remove the pocket door system that is in the hallway. This includes the fascia that is around the rail system, the door, and the trimmings to try to trim down what is causing the squeeking-

WS	WINTERIZE WATER SYSTEM & TRAPS -SELF CONTAINED -	E	17843	CAMPB
	TOWABLE			

Job #	Part No	Description	PARTS	Bill to	Qty	Price	Total
-------	---------	-------------	-------	---------	-----	-------	-------

WS	071247312003	-50 ANTIFREEZE/	1 GALLON	E-17843	3	9.62	28.86
----	--------------	-----------------	----------	---------	---	------	-------

Job#	Lab Code	Description	LABOUR	Mech	Bill to	Hrs	Rate	Total
------	----------	-------------	--------	------	---------	-----	------	-------

ARR01	Z992	MISC LABOUR CODE	(WARR JGK	W-1020	0.50	140.00	70.00
ARR01	Z992	MISC LABOUR CODE	(WARR JGK	W-1020	0.00	140.00	0.00
ARR02	Z992	MISC LABOUR CODE	(WARR JGK	W-1020	0.50	140.00	70.00
ARR02	Z992	MISC LABOUR CODE	(WARR JGK	W-1020	0.00	140.00	0.00
ARR03	Z992	MISC LABOUR CODE	(WARR JGK	W-1020	0.35	140.00	49.00
ARR03	Z992	MISC LABOUR CODE	(WARR JGK	W-1020	0.00	140.00	0.00
ARR03	Z992	MISC LABOUR CODE	(WARR JGK	W-1020	0.15	140.00	21.00
ARR04	Z992	MISC LABOUR CODE	(WARR JGK	W-1020	0.50	140.00	70.00
ARR04	Z992	MISC LABOUR CODE	(WARR JGK	W-1020	0.00	140.00	0.00
ARR04	WARR	MANUFACTURER WARRANTY	JGK	W-1020	0.50	140.00	70.00
ARR05	Z992	MISC LABOUR CODE	(WARR JGK	W-1020	0.50	140.00	70.00
ARR05	Z992	MISC LABOUR CODE	(WARR JGK	W-1020	0.00	140.00	0.00
WS	W495	WINTERIZE RV	(WATER SY	JGK E-17843	0.00	130.00	0.00

Continued on page 3

Work Order : 12845

```
*****
Job#  Lab Code  Description   LABOUR   Mech Bill to    Hrs    Rate    Total
*****
WS W495      WINTERIZE RV (WATER SY JGK  E-17843    0.00   130.00    0.00
*****
```

```
*****
Job #  Excode   Description   EXTRAS      bill to    Qty    Price    Total
*****
ARR01  SSE       SHOP SUPPLIES - EXTERNAL  W-1020    1.00    0.00    0.00
WS  J-ADJ      QUOTE ADJUSTMENT          E-17843    1.00   76.14   76.14
*****
```

```
*****
                                BILLINGS SUMMARY
Type Bill Id      Parts    Labour    Sublet    Extras    Tax    Total
*****
E   17843         28.86      0.00      0.00     76.14     5.80   110.80
W   1020          0.00     420.00      0.00      0.00      0.00   420.00

Totals          28.86     420.00      0.00     76.14     5.80   530.80
*****
```

&k2S
&k0S