



Warranty Claim Form

Date: 11/11/2025

1127 Greenway RV Sales & Service
8220 State Hwy 13 South
Wisconsin Rapids, WI 54494
United States
Ph. 715-325-5170
mail@greenwayrv.com

General Information

573TT3125T7703703
Transcend 245RLT
Retail Purchase Date: null
Work Started: 10/21/2025
Work Completed: 10/21/2025

Claim Status: Paid
Dealer Work Order #: 13004B
Unit Offline Date: 10/2/2025

Claim #: 942428
Labor: \$84.00
Parts: \$24.17
Shipping: \$0.00
Total: \$108.17

Notes: JPH 10-27-25

Dealer Information

1127 Greenway RV Sales & Service
8220 State Hwy 13 South
Wisconsin Rapids, WI 54494
United States

715-325-5170
mail@greenwayrv.com
Approved Labor Rate: \$140.00

Customer Information

Operation Line # 1

Flat Rate Code: 610011 Moldings/Trims - Repair (per Piece) *Fault Code:* Improper Installation/Build

Problem: The baton strip in the cabinet above the sink fell off.

Hours: .1

Cause: The baton strip in the cabinet above the kitchen sink fell.

Amount: 14.00

Remedy: Resecured and nailed it back in place.

Sublet Repairs: \$0.00

Manufacturer #:

Model #:

Serial #:

Operation Line # 2

Flat Rate Code: 310008 Termination (Gate) Valves - Repair/Replace- *Fault Code:* Damaged/Maintenance
Below Floor (not enclosed)

Problem: Due to the placement of the gray tank valve, it is allowing water to flow from one tank to the other and will fill both tanks off one appliance, a second gate valve will need to be put in.

Hours: .5

Cause: There was only one gray tank termination valve for two tanks and the placement of it cased one appliance to fill both tanks.

Amount: 70.00

Remedy: Put in another termination valve.

Sublet Repairs:
\$0.00

Manufacturer #:

Model #:

Serial #:

<u>Part</u>	<u>Description</u>	<u>Return Tag #</u>	<u>Qty</u>	<u>Units</u>	<u>Amount</u>
960204 Miscellaneous Part for claim use only	Miscellaneous Part for claim use only		1	1	24.17