

GREENEWAY, INC.
8220 STATE HWY 13 SOUTH
WISCONSIN RAPIDS WI
US
54494
(715) 325-5170

WORK ORDER # 13140B

Date In:	05 JAN 26	Author:	MGRAY
Promised Date:	31 DEC 25	Stock No:	11557
:	:	Year:	2026
Customer Name:	1020 - GRAND DESIGN	Manufacturer:	GRAND DESIGN
Address:	11333 COUNTY RD 2	Brand:	TRANSCEND ONE
:	MIDDLEBURY, IN	Model:	131DL
Postal/Zip:	46540	Miles/Hrs:	0
Phone#(res):	888-825-2820	Exterior Color:	:
Phone#(bus):	:	Unit Type:	TT-TRAVEL TRAILER
Cell Phone:	:	License#:	:
Email:	NONE	Tag#:	:
Purchased Date:	:	:	:
Delivery Date:	:	:	:
InService Date:	:	:	:
Serial#:	573TT1616T8843029	:	:

```
*****
Job #   Description      JOB INFORMATION      Type Bill To
*****
WARR    COMPLAINT:  WARRANTY REPAIR 1 - The exterior of      W    1020    GRAND
        window next to entrance door has large
        amounts of clear silicone smeared around
        it
        CAUSE:      Mfg had a lot of excess clear silicone
        around window done very sloppy
        CORRECTION: I used quick solve and a scraper to
        remove the silicone from around the
        window REQUEST: .5
WARR    COMPLAINT:  WARRANTY REPAIR 2 -Refer door has sticky W    1020    GRAND
        substance near top of the door
        CAUSE:      Mfg had silicone smeared on face of
        refer
        CORRECTION: I used quick solve to remove the
        silicone REQUEST:.1
WARR    COMPLAINT:  WARRANTY REPAIR 3 - Deep staple holes in W    1020    GRAND
        cabinets and walls in unit
        CAUSE:      Deep holes in paneling and cabinets from
        staples
        CORRECTION: I used putty and filled the holes
        REQUEST:.4
WARR    COMPLAINT:  WARRANTY REPAIR 4 -Toilet is leaking at  W    1020    GRAND
        its base
        CAUSE:      The toilet bolts needed tightening
        CORRECTION: Removed caps tightened bolts wiped up
        water that was from toilet and ran water
        through toilet let it sit and there is
        no longer any water leaking from toilet
*****
```

Continued on page 2

Work Order : 13140B

```

*****
Job #   Description                JOB INFORMATION                Type Bill To
*****
                                REQUEST: .2
WARR    COMPLAINT:  WARRANTY REPAIR 5 - White ceiling trim    W    1020    GRAND
                                has black marks on it
                                CAUSE:  Black marks from mfg
                                CORRECTION:  Used quick solve to remove marks on all
                                3 ceiling trim  REQUEST: .2
WARR    COMPLAINT:  WARRANTY REPAIR 6 - ODS beneath          W    1020    GRAND
                                emergency window there is a nail
                                protruding out of wall beneath seam tape
                                CAUSE:  Nail not set
                                CORRECTION:  I set nail so it no longer is bulging
                                from beneath seam tape  REQUEST: .1

```

```

*****
Job#  Lab Code  Description  LABOUR  Mech Bill to  Hrs  Rate  Total
*****
ARR01 Z992      MISC LABOUR CODE (WARR HOD W-1020  0.49  140.00  68.60
ARR01 Z992      MISC LABOUR CODE (WARR HOD W-1020  0.01  140.00   1.40
ARR02 Z992      MISC LABOUR CODE (WARR HOD W-1020  0.49  140.00  68.60
ARR02 Z992      MISC LABOUR CODE (WARR HOD W-1020  0.01  140.00   1.40
ARR03 Z992      MISC LABOUR CODE (WARR HOD W-1020  0.45  140.00  63.00
ARR03 Z992      MISC LABOUR CODE (WARR HOD W-1020  0.05  140.00   7.00
ARR04 Z992      MISC LABOUR CODE (WARR HOD W-1020  0.50  140.00  70.00
ARR05 Z992      MISC LABOUR CODE (WARR HOD W-1020  0.49  140.00  68.60
ARR05 Z992      MISC LABOUR CODE (WARR HOD W-1020  0.01  140.00   1.40
ARR06 Z992      MISC LABOUR CODE (WARR HOD W-1020  0.49  140.00  68.60
ARR06 Z992      MISC LABOUR CODE (WARR HOD W-1020  0.01  140.00   1.40

```

```

*****
Job #  Excode  Description  EXTRAS  bill to  Qty  Price  Total
*****
ARR01  SSE     SHOP SUPPLIES - EXTERNAL  W-1020  1.00  0.00  0.00

```

```

*****
                                BILLINGS SUMMARY
Type Bill Id  Parts  Labour  Sublet  Extras  Tax  Total
*****
W    1020      0.00   420.00   0.00   0.00   0.00   420.00
                                Totals      0.00   420.00   0.00   0.00   0.00   420.00

```

&k2S
&k0S