

GREENEWAY, INC.
8220 STATE HWY 13 SOUTH
WISCONSIN RAPIDS WI
US
54494
(715) 325-5170

WORK ORDER # 13150B

Date In:	02 DEC 25	Author:	MGRAY
Promised Date:	31 DEC 25	Stock No:	11563
:	:	Year:	2026
Customer Name:	1000 - GREENEWAY RV SA	Manufacturer:	GRAND DESIGN
Address:	8220 STATE HWY 13 SOUT	Brand:	TRANSCEND
:	WISCONSIN RAPIDS, WI	Model:	335BHT
Postal/Zip:	54494	Miles/Hrs:	0
Phone#(res):	800-758-2272	Exterior Color:	:
Phone#(bus):	:	Unit Type:	TT-TRAVEL TRAILER
Cell Phone:	:	License#:	:
Email:	NONE	Tag#:	DB: 12/4
Purchased Date:	:	:	:
Delivery Date:	:	:	:
InService Date:	:	:	:
Serial#:	573TT3725T7703868	:	:

Job #	Description	JOB INFORMATION	Type	Bill To
WARR	COMPLAINT:	WARRANTY REPAIR 1 - Bottom of bunk door is peeling up	W	1020 GRAND
	CAUSE:	Peeled bottom edge of door		
	CORRECTION:	Used sand paper to lightly sand off the bottom edge then used white paint pen to cover REQ: .30		
WARR	COMPLAINT:	WARRANTY REPAIR 2 - deep staple holes inside cabinets	W	1020 GRAND
	CAUSE:	Deep holes from staples not filled		
	CORRECTION:	Filled deep holes with putty then wiped down with murpheys oil soap REQ: .60		
WARR	COMPLAINT:	WARRANTY REPAIR 3 - while running the shower in bathroom water is coming from the corner	W	1020 GRAND
	CAUSE:	The stall did not have sealant at bottom and corner of shower stall		
	CORRECTION:	I checked under shower to see if there was a leak at drdin or back of shower faucet nothing leaking at either I then checked for sealant and there was none so sealed with clear silicone then tested and now water is not leaking out on to the floor like it was REQ: .30		
WARR	COMPLAINT:	WARRANTY REPAIR 4 - The trim on ceiling above love seat the nails are not set and the tape looks dirty on the edge of it	W	1020 GRAND
	CAUSE:	Protruding nails		

Continued on page 2

Work Order : 13150B

```

*****
Job #      Description      JOB INFORMATION      Type Bill To
*****
CORRECTION: Set nails then cleaned up the tape
REQ: .30

```

```

*****
Job#  Lab Code  Description  LABOUR  Mech Bill to  Hrs  Rate  Total
*****
ARR01 Z992      MISC LABOUR CODE (WARR HOD W-1020  0.50  140.00  70.00
ARR02 Z992      MISC LABOUR CODE (WARR HOD W-1020  0.50  140.00  70.00
ARR03 Z992      MISC LABOUR CODE (WARR HOD W-1020  0.50  140.00  70.00
ARR04 Z992      MISC LABOUR CODE (WARR HOD W-1020  0.50  140.00  70.00

```

```

*****
                        BILLINGS SUMMARY
Type Bill Id      Parts      Labour      Sublet      Extras      Tax      Total
*****
W      1020      0.00      280.00      0.00      0.00      0.00      280.00

Totals      0.00      280.00      0.00      0.00      0.00      280.00

```

&k2S
&k0S