



8220 State Hwy 13 South
Wisconsin Rapids, WI 54494

(715) 325-5170
mail@greenewayrv.com
www.greenewayrv.com

[spreading the joy of the camping lifestyle]

W/O: 8611
Promised Date:
25 DEC 23



WO #: 8611

Customer Name: 16836 - BECK, JESSICA
Address: 17 HUNTERS COURT
FOND DU LAC, WI
Postal/Zip: 54937
Phone#(res): 3142461451
Phone#(bus):
Cell Phone:
Email: j.guenther08@gmail.com

Date In: 24 APR 23
Promised Date: 25 DEC 23

Purchased Date: 01 MAY 23
Delivery Date: 09 MAY 23
InService Date:
Serial#: 573TE2621N3429133

Author: MGRAY
Stock No: 10521
Year: 2022
Manufacturer: GRAND DESIGN
Brand: IMAGINE XLS
Model: 22RBE
Miles/Hrs: 0
Exterior Color:
Unit Type: TT-TRAVEL TRAILER
License#:
Tag#: CALLED 10/20 UNIT DONE

Job #1 - Warranty

COMPLAINT: LADDER SPLIT IN THE BOTTOM LOOP

CAUSE: CRACK IN THE BOOTM LOOP OF LADDER, LADDER DID NOT HAVE A DRAIN HOLE AND
FILLED WITH WATER AND FROZE CAUSING IT TO SPLIT

CORRECTION: WILL NEED TO REPLACE LADDER.

Labor

Job #	Description	Total
1	MANUFACTURER WARRANTY REPAIR	57.50

Parts

Part #	Description	Qty	Price	Total
82200488	LADDER EXTERIOR 12X96 BLACK CENTER MOUNT 5 STEP GD133	1.00	135.86	135.86

Other Services

Code	Description	Qty	Price	Total
FRT	FREIGHT FOR JOB 1	1.00	161.43	161.43

Subtotal for Job #1: 354.79

Parts Total: 135.86
Labour Total: 57.50
Sublet Total: 0.00
Extras Total: 161.43
WORK ORDER TOTAL: 354.79

CUSTOMERS CLEAR RECEIPT

The above described property has been received, and after having examined the work done, the material furnished, both the work and material has been found to be satisfactory.
I agree that any goodwill repairs are in no way an admission that the vehicle suffers from any defect or issue, or that the repair should be covered under warranty.

Customer Signature : _____

Date: 07 May 2024

Customer #: 16836
BECK, JESSICA

