



8220 State Hwy 13 South  
Wisconsin Rapids, WI 54494

[ spreading the joy of the camping lifestyle ]

(715) 325-5170  
mail@greenewayrv.com  
www.greenewayrv.com

W/O: 8741B  
Promised Date:  
24 DEC 23

WO #: 8741B

Customer Name: 8225 - BENNINGTON,  
MICHAEL

Address: 2135 PORTLAND AVE  
BELOIT, WI

Postal/Zip: 53511

Phone#(res):

Phone#(bus):

Cell Phone: 608-346-5830

Email: benningtonmj@yahoo.com

Date In: 24 MAY 23

Promised Date: 31 DEC 23

Purchased Date: 05 MAY 23

Delivery Date: 24 MAY 23

InService Date:

Serial#: 573TR3821N3343120

Author: TPASSER

Stock No: 10487

Year: 2022

Manufacturer: GRAND DESIGN

Brand: REFLECTION TT

Model: 315RLTS

Miles/Hrs: 0

Exterior Color:

Unit Type: TT-TRAVEL TRAILER

License#:

Tag#: 7/22 & 8/1 - LEFT VM TO SCHED  
MS 8/14 VM LEFT TO SCHEDULE MS

**Job #WARR01 - Warranty**

COMPLAINT: WARRANTY REPAIR 1 - WHEN DOING SHOW THROUGH CUSTOMER INSPECTED THE ROOF AND FOUND A STAPLE POKING UP UNDER RUBBER

CAUSE: MFG

CORRECTION: TO REPAIR WE WILL NEED TO REMOVE LADDER, SCREW TRACK ON THE REAR AND THE SIDE. WE WILL THEN NEED TO PEEL UP THE ROOFING MATERIAL AND REMOVE STAPLE. AFTER STAPLE IS REMOVED WE WILL NEED TO REGLUE THE ROOFING MATERIAL. REATTACH THE SCREW TRACKS AND REATTACH LADDER-WILL NEED TO REDICOR AREA THAT WERE AFFECTED.

ALSO THIS FOUND AT TIME OF SHOW THRU FOR CUSTOMER AND IS GOING TO BE PERMENTLY PARKED AND CUSTOMER NEEDS SERVICE CALL FOR THIS REPAIR AS WELL TO WESTFEILD WI.

\*\*\*\*\*NOTES approved 1 hour to cut membrane ,remove staple and add vent cap- Part pulled and put by Joes area\*\*\*\*\*

**Labor**

Job #	Description	Total
WARR01	MISC LABOUR CODE (WARRANTY)	N/C

**Subtotal for Job #WARR01: 0.00**

**Job #WARR02 - Warranty**

WARRANTY REPAIR 2 - PLEASE NOTE THAT THERE WERE 2 MORE BLEMISHES ON THE ROOF. THEY LOOK TO BE COSMETIC BUT CUSTOMER WANTS THIS NOTED INCASE THERE ARE ANY ISSUES.

**Labor**

Job #	Description	Total
WARR02	MISC LABOUR CODE (WARRANTY)	N/C

**Subtotal for Job #WARR02: 0.00**

**Job #1 - Internal**

INTERIOR ROOF AC DAMAGED WHEN WE INSTALLED IT . NEED REPLACEMENT ORDERED

Customer #: 8225  
BENNINGTON, MICHAEL



W/O: 8741B  
Promised Date: 31 DEC 23

Subtotal for Job #1: 0.00

**Job #2 - Warranty**

ADDED 6/1 LOST TANK HANDLE FOR DRAIN BLACK TANK PICS IN WO

Subtotal for Job #2: 0.00

Parts Total: 0.00

Labour Total: 0.00

Sublet Total: 0.00

Extras Total: 0.00

**WORK ORDER TOTAL: 0.00**

**CUSTOMERS CLEAR RECEIPT**

The above described property has been received, and after having examined the work done, the material furnished, both the work and material has been found to be satisfactory.

I agree that any goodwill repairs are in no way an admission that the vehicle suffers from any defect or issue, or that the repair should be covered under warranty.

Customer Signature : \_\_\_\_\_

Date: 07 May 2024



Customer #: 8225  
BENNINGTON, MICHAEL

