



8220 State Hwy 13 South
Wisconsin Rapids, WI 54494

[spreading the joy of the camping lifestyle]

(715) 325-5170
mail@greenewayrv.com
www.greenewayrv.com

W/O: 9270B
Promised Date:
24 MAY 24

WO #: 9270B

Customer Name: 16898 - GAUTHIER, GARY
Address: 3304 CUMBERLAND AVENUE
STURGEON BAY, WI

Postal/Zip: 54235
Phone#(res): 920-559-2703
Phone#(bus):
Cell Phone:
Email: garyrg@sbcglobal.net

Date In: 11 AUG 23
Promised Date: 31 MAY 24

Purchased Date: 13 JUN 23
Delivery Date: 14 AUG 23
InService Date:
Serial#: 573FR3421R3347614

Author: MGRAY
Stock No: 10949
Year: 2024
Manufacturer: GRAND DESIGN
Brand: REFLECTION 150 SERIES
Model: 295RL
Miles/Hrs: 0
Exterior Color:
Unit Type: FW-FIFTH WHEEL
License#:
Tag#: APT 5/6 - 11:20

Job #WARR01 - Warranty

COMPLAINT: WARRANTY REPAIR 1 - freezer door glass has a deep scratch in its finish ON DAF

CAUSE: Mfg

CORRECTION: Order new freezer door glass insert grey colored FURRION M# FCR10DCGTA

Labor

Job #	Description	Total
WARR01	MISC LABOUR CODE (WARRANTY)	57.50

Parts

Part #	Description	Qty	Price	Total
82201136	REFRIGERATOR FREEZER DOOR ASSEMBLY ONLY STAINLESS STEEL GLASS DOOR F/ FCR10-NR FCR08-NR (FURRION C-FCR10DCGTA-048)	1.00	333.53	333.53

Other Services

Code	Description	Qty	Price	Total
SSE	SHOP SUPPLIES - EXTERNAL	1.00	0.00	0.00
FRT	FREIGHT FOR FREEZER DOOR	1.00	15.06	15.06

Subtotal for Job #WARR01: 406.09

Job #WARR02 - Warranty

COMPLAINT: WARRANTY REPAIR 2 - Microwave has scratches that will arc on daf

CAUSE: Mfg

CORRECTION: Order new microwave FURRION M#FMSMA15-SS

Labor

Job #	Description	Total
WARR02	MISC LABOUR CODE (WARRANTY)	57.50

Parts

Part #	Description	Qty	Price	Total
82200698	MICROWAVE OTR NON CONVECTION STAINLESS STEEL 1.6 CF FURRION FMSMA15-SS	1.00	505.05	505.05



Customer #: 16898
GAUTHIER, GARY



Other Services

Code	Description	Qty	Price	Total
FRT	FREIGHT FOR JOB 2	1.00	42.00	42.00

Subtotal for Job #WARR02: 604.55

Job #WARR03 - Warranty

COMPLAINT: WARRANTY REPAIR 3 - screen coming out in rear window daf

CAUSE: Mfg

CORRECTION: Reinserted spline in window screen track

Labor

Job #	Description	Total
WARR03	MISC LABOUR CODE (WARRANTY)	57.50

Subtotal for Job #WARR03: 57.50

Job #WARR04 - Internal

COMPLAINT: WARRANTY REPAIR 4 - table has a scuff on edge

CAUSE: Mfg

CORRECTION: I am noting in case customer would like one ordered because of the scuff

Labor

Job #	Description	Total
WARR04	MISC LABOUR CODE (WARRANTY)	N/C

Subtotal for Job #WARR04: 0.00

Job #WARR05 - Warranty

COMPLAINT: WARRANTY REPAIR 5 -screen next to dining table is loose

CAUSE: Mfg

CORRECTION: Pushed spline back into place

Labor

Job #	Description	Total
WARR05	MISC LABOUR CODE (WARRANTY)	57.50

Subtotal for Job #WARR05: 57.50

Job #WARR06 - Warranty

COMPLAINT: WARRANTY REPAIR 6 - gouge next to pantry

CAUSE: Gouge mfg

CORRECTION: Used putty to cover gouge

Labor

Job #	Description	Total
WARR06	MISC LABOUR CODE (WARRANTY)	57.50

Subtotal for Job #WARR06: 57.50

Job #WARR09 - Warranty

COMPLAINT: WARRANTY REPAIR 9 - floor has a little ding in it

CAUSE: Mfg

CORRECTION: Used putty to cover then put sealer over that




Labor		
Job #	Description	Total
WARR09	MISC LABOUR CODE (WARRANTY)	57.50
Subtotal for Job #WARR09:		57.50

Job #WARR10 - Warranty

WARRANTY REPAIR 10 - TRIM IS DISCOLORED BY REFER DOOR. picture under line from cmr

Labor		
Job #	Description	Total
WARR10	MISC LABOUR CODE (WARRANTY)	57.50
Subtotal for Job #WARR10:		57.50



Parts Total:	838.58
Labour Total:	402.50
Sublet Total:	0.00
Extras Total:	57.06
WORK ORDER TOTAL:	1,298.14

CUSTOMERS CLEAR RECEIPT

The above described property has been received, and after having examined the work done, the material furnished, both the work and material has been found to be satisfactory.
 I agree that any goodwill repairs are in no way an admission that the vehicle suffers from any defect or issue, or that the repair should be covered under warranty.

Date: 07 May 2024

Customer Signature : _____

W/O: 9270B
 Promised Date: 31 MAY 24



Customer #: 16898
 GAUTHIER, GARY

