



11333 COUNTY ROAD 2
MIDDLEBURY IN 46540

PAYMENT INFORMATION

DATE: October 9, 2024
CHECK NUMBER: 574799
AMOUNT PAID: \$2,104.67
ACCOUNT NUMBER: XXXXXX8598
TRACE NUMBER: 0000000060932952
VENDOR ID: 1312
VENDOR NAME: Greeneway RV Sales & Service



0000002982-1 CPL0 2A 28324-2 VN - A0216664
GREENEWAY RV SALES & SERVICE
 8220 STATE HWY 13 SOUTH
 WISCONSIN RAPIDS WI 54494



283405400101002982000100000000

Date	Invoice Number	Description	Gross Amount	Discount	Net Amount
10/03/2024	Claim:828384 VIN:P9924075	10218 ✓	\$1,704.83	\$0.00	\$1,704.83
10/04/2024	Claim:832526 VIN:PAA15100	10271 ✓	\$218.50	\$0.00	\$218.50
10/07/2024	Claim:841881 VIN:P6644014	11238 ✓	\$181.34	\$0.00	\$181.34
Totals			\$2,104.67	\$0.00	\$2,104.67

WARR COMPLAINT: CUSTOMER STATES THE FRONT GRAY WATER FOR W 1020 GRAND
 THE KITCHEN SINK DUMP PULL HANDLE DOES
 NOT FEEL LIKE IT IS CONNECTED- CUSTOMER
 SAYS IT FEELS LIKE THE LEVER DOES NOT
 OPEN OR PULL-
 CAUSE: The gate valve broke into multiple
 pieces. At first glance, I thought their
 wasn't even a gate valve connected. I

Continued on page 2