

GREENEWAY, INC.
8220 STATE HWY 13 SOUTH
WISCONSIN RAPIDS WI
US
54494
(715) 325-5170

WORK ORDER # 11594B

Date In: 02 JAN 25 Author: MGRAY
Promised Date: 04 JUL 25 Stock No: 11192
: Year: 2025
Customer Name: 17566 - MORIARITY, MIC Manufacturer: GRAND DESIGN
Address: 509 W. 10TH ST Brand: TRANSCEND ONE
: MORRIS, MN Model: 151BH
Postal/Zip: 56267 Miles/Hrs: 0
Phone#(res): 6074255720 Exterior Color:
Phone#(bus): Unit Type: TT-TRAVEL TRAILER
Cell Phone: License#:
Email: moriarity001@comcast.n Tag#: PU@ST- 11/22@11
Purchased Date: :
Delivery Date: :
InService Date: :
Serial#: 573TT2015S8832505 :

Job # Description JOB INFORMATION Type Bill To

ISR0 COMPLAINT: INTERNAL STOCK REPAIR 01. I went to W 1020 GRAND
finish prep unit it was suppose to go
last week customer changed date to this
week it was taken out of show room last
week by Cody and Jess and brought into
shop for showthru after customer
canceled and rescheduled for this week
unit was taken outside and not
winterized . Toilet valve is broken will
need to replace that and possibly
faucets
CAUSE: Employee Never winterized unit before
taking back out side
CORRECTION: Removed toilet diagnosed that the valve
was broken from freezing removed and
replaced valve. bench tested it is
working as it should no leaking . I then
thawed out water pump and ran water
through all faucets checked all
connections and drains no leaking and
pump works as it should . I then hooked
up city water tested and checked
everything no leaking . I will be
winterizing time in a different line
please adjust this time to be accurate
REQUESTING .50 FOR LABOR
WARR COMPLAINT: WARRANTY REPAIR 1 - the linoleum has b W 1020 GRAND
hole in the floor in kitchen

Continued on page 2

Work Order : 11594B

```

*****
Job #   Description           JOB INFORMATION           Type Bill To
*****
      CAUSE:           Hole in lino
      CORRECTION:      Used putty and sealer to fill hole then
                      seal it  REQUESTING .50 LABOR
*****

```

```

*****
Job # Part No      Description           PARTS      Bill to  Qty      Price      Total
*****
ISR01 713814072827 VALVE KIT, WATER           W-1020     1        65.07      65.07
*****

```

```

*****
Job#  Lab Code  Description           LABOUR      Mech Bill to      Hrs      Rate      Total
*****
ISR01 Z991      MISC LABOUR CODE (INTE HOD  W-1020     0.50    115.00     57.50
ARR01 Z992      MISC LABOUR CODE (WARR HOD  W-1020     0.50    115.00     57.50
*****

```

```

*****
Job #  Excode   Description           EXTRAS      bill to  Qty      Price      Total
*****
ISR01  SSE      SHOP SUPPLIES - EXTERNAL  W-1020     1.00     0.00      0.00
*****

```

```

*****
                                BILLINGS SUMMARY
Type Bill Id      Parts      Labour      Sublet      Extras      Tax      Total
*****
W      1020      65.07      115.00      0.00      0.00      0.00      180.07
      Totals      65.07      115.00      0.00      0.00      0.00      180.07
*****

```

&k2S
&k0S