



1025 WI-77 Minong WI US 54859 www.linkrvedirect.com

Invoice
\$0.00

RO# : 39334 Tag# : T11P0067

Check-in: Thu Sep 11, 2025 | 2:44 PM
Ready for Pickup: Tue Apr 7, 2026 | 2:49 PM
Promise Time: Tue Sep 16, 2025 | 6:00 PM

Customer
linkautomotive - 2174
PD7155200709I
Customer
1235491
+1 - (715) 466 - 2222
no@email.com
1025 WI-77
Minong, WI 54859

Pickup-Customer
Same as Customer

Billing-Customer
Same as Customer

Vehicle
2026 JAYCO JAYLOFT
BUNGALOW
1UJBC0BV3T11P0067
1 Mi In
Stock #: 26-13

Service Advisor
BECKY DALEIDEN
beckl

A.	MISCELLANEOUS	DEALER STATES LOWER CUPBOARD IN BEDROOM HAS LOOSE HINGE	Warranty Pay	\$0.00
----	---------------	---	--------------	--------

Job added by BECKY DALEIDEN on Thu Sep 11, 2025 | 2:44 PM

1. Screw hole was reamed out.

Op:1 MISCELLANEOUS -MISCELLANEOUS

Labor Sale: \$0.00

Labor Cost: \$6.30

Technician	Certification Number	Actual Hours	Assigned Bill Hours	Flag Hours	Labor Sale	Labor Cost
matthewl	-	0.08	0.3	0.3	\$0.00	\$6.30

1. Used slightly more aggressive screw to refasten.

2. .3 hours requested

Total Labor Sale
\$0.00

Total Labor Cost
\$6.30

Total Parts Sale
\$0.00

Total Parts Cost
\$0.00

B.	MISCELLANEOUS	DEALER STATES SCRATCH ON INTERIOR TRIM ON SLIDE OUT	Warranty Pay	\$0.00
----	---------------	---	--------------	--------

Job added by BECKY DALEIDEN on Thu Sep 11, 2025 | 2:44 PM

1. Scratched





1025 WI-77 Minong WI US 54859 www.linkrvidirect.com

Invoice
\$0.00

RO# : 39334 Tag# : T11P0067

Check-in: Thu Sep 11, 2025 | 2:44 PM
Ready for Pickup: Tue Apr 7, 2026 | 2:49 PM
Promise Time: Tue Sep 16, 2025 | 6:00 PM

Customer
linkautomotive - 2174
PD7155200709I
Customer
1235491
+1 - (715) 466 - 2222

Billing-Customer
Same as Customer

Vehicle
2026 JAYCO JAYLOFT
BUNGALOW
1UJBC0BV3T11P0067

Service Advisor
BECKY DALEIDEN
beckl

Op.1 MISCELLANEOUS -MISCELLANEOUS

Labor Sale: \$0.00

Labor Cost: \$0.00

Technician	Certification Number	Actual Hours	Assigned Bill Hours	Flag Hours	Labor Sale	Labor Cost
matthewl	-	0.06	0	0	\$0.00	\$0.00

1. Recommend matching paint or new trim
2. 1 hour requested

Total Labor Sale
\$0.00

Total Labor Cost
\$0.00

Total Parts Sale
\$0.00

Total Parts Cost
\$0.00

C.	MISCELLANEOUS	DEALER STATES CAULK ABOVE REAR BUMPER	Warranty Pay	\$0.00
----	---------------	---------------------------------------	--------------	--------

Job added by BECKY DALEIDEN on Thu Sep 11, 2025 | 2:44 PM

1. Sloppy caulk

Op.1 MISCELLANEOUS -MISCELLANEOUS

Labor Sale: \$0.00

Labor Cost: \$0.00

Technician	Certification Number	Actual Hours	Assigned Bill Hours	Flag Hours	Labor Sale	Labor Cost
matthewl	-	0.1	0	0	\$0.00	\$0.00

1. Removed caulk with citrol, soft rag and plastic scraper
2. .3 hours requested

Total Labor Sale
\$0.00

Total Labor Cost
\$0.00

Total Parts Sale
\$0.00

Total Parts Cost
\$0.00





1025 WI-77 Minong WI US 54859 www.linkrvdirect.com

Invoice
\$0.00

RO# : 39334 Tag# : T11P0067

Check-in: Thu Sep 11, 2025 | 2:44 PM

Ready for Pickup: Tue Apr 7, 2026 | 2:49 PM

Promise Time: Tue Sep 16, 2025 | 6:00 PM

Customer
linkautomotive - 2174
PD7155200709I
Customer
1235491
+1 - (715) 466 - 2222

Billing-Customer
Same as Customer

Vehicle
2026 JAYCO JAYLOFT
BUNGALOW
1UJBC0BV3T11P0067

Service Advisor
BECKY DALEIDEN
beckl

D.	MISCELLANEOUS	DEALER STATES SLIDING DOOR NOT LINE UP PROPERLY	Warranty Pay	\$0.00
----	---------------	---	--------------	--------

Job added by BECKY DALEIDEN on Thu Sep 11, 2025 | 2:44 PM

1. Bent door frame

Op.1 MISCELLANEOUS -MISCELLANEOUS

Labor Sale: \$0.00

Labor Cost: \$0.00

Technician	Certification Number	Actual Hours	Assigned Bill Hours	Flag Hours	Labor Sale	Labor Cost
matthewl	-	0.16	0	0	\$0.00	\$0.00

1. Sliding door frame is bent and crooked. Door won't latch, nor close all the way. Recommend new frame/door

2. 6 hours requested

Total Labor Sale
\$0.00

Total Labor Cost
\$0.00

Total Parts Sale
\$0.00

Total Parts Cost
\$0.00

E.	MISCELLANEOUS	DEALER STATES SCREEN DOOR TO SLIDING DOOR IS NOT ATTACHED	Warranty Pay	\$0.00
----	---------------	---	--------------	--------

Job added by BECKY DALEIDEN on Thu Sep 11, 2025 | 2:44 PM

1. Frame for sliding door is bent and damaged.

Op.1 MISCELLANEOUS -MISCELLANEOUS

Labor Sale: \$0.00

Labor Cost: \$0.00

Technician	Certification Number	Actual Hours	Assigned Bill Hours	Flag Hours	Labor Sale	Labor Cost
matthewl	-	0.08	0	0	\$0.00	\$0.00

1. No sense in installing a good screen door onto a frame that needs replacement. Recommend addressing later.





1025 WI-77 Minong WI US 54859 www.linkrvdirect.com

Invoice
\$0.00

RO# : 39334 Tag# : T11P0067

Check-in: Thu Sep 11, 2025 | 2:44 PM

Ready for Pickup: Tue Apr 7, 2026 | 2:49 PM

Promise Time: Tue Sep 16, 2025 | 6:00 PM

Customer
linkautomotive - 2174
PD71552007091
Customer
1235491
+1 - (715) 466 - 2222

Billing-Customer
Same as Customer

Vehicle
2026 JAYCO JAYLOFT
BUNGALOW
1UJBC0BV3T11P0067

Service Advisor
BECKY DALEIDEN
beckl

Op.1 MISCELLANEOUS -MISCELLANEOUS

Labor Sale: \$0.00

Labor Cost: \$0.00

2. .3 hours requested

Total Labor Sale
\$0.00

Total Labor Cost
\$0.00

Total Parts Sale
\$0.00

Total Parts Cost
\$0.00

F.	MISCELLANEOUS	DEALER STATES TRAILER LEANS TO DRIVERS SIDE	Warranty Pay	\$0.00
----	---------------	---	--------------	--------

Job added by BECKY DALEIDEN on Thu Sep 11, 2025 | 2:44 PM

1. Slideout weight?

Op.1 MISCELLANEOUS -MISCELLANEOUS

Labor Sale: \$0.00

Labor Cost: \$0.00

Technician	Certification Number	Actual Hours	Assigned Bill Hours	Flag Hours	Labor Sale	Labor Cost
matthewl	-	17.16	0	0	\$0.00	\$0.00

1. Driver side front is 1 1/2" lower on driver side front corner. Driver side rear is 1 1/4" lower. Documenting for office.

2. we do not know the correction for this please have jayco advise on how they want to fix this

Total Labor Sale
\$0.00

Total Labor Cost
\$0.00

Total Parts Sale
\$0.00

Total Parts Cost
\$0.00

G.	MISCELLANEOUS	DEALER STATES TRAVEL LOCK HAS LAPSEAL ON IT	Warranty Pay	\$0.00
----	---------------	---	--------------	--------

Job added by BECKY DALEIDEN on Thu Sep 11, 2025 | 2:44 PM

1. Was not lapseal.





1025 WI-77 Minong WI US 54859 www.linkrvdirect.com

Invoice
\$0.00

RO# : 39334 Tag# : T11P0067

Check-in: Thu Sep 11, 2025 | 2:44 PM

Ready for Pickup: Tue Apr 7, 2026 | 2:49 PM

Promise Time: Tue Sep 16, 2025 | 6:00 PM

Customer
linkautomotive - 2174
PD7155200709I
Customer
1235491
+1 - (715) 466 - 2222

Billing-Customer
Same as Customer

Vehicle
2026 JAYCO JAYLOFT
BUNGALOW
1UJBC0BV3T11P0067

Service Advisor
BECKY DALEIDEN
beckl

Op.1 MISCELLANEOUS -MISCELLANEOUS

Labor Sale: \$0.00

Labor Cost: \$0.00

Technician	Certification Number	Actual Hours	Assigned Bill Hours	Flag Hours	Labor Sale	Labor Cost
matthewl	-	0.13	0	0	\$0.00	\$0.00

1. Washed off during wash. No issue.

2. 0 hours requested

Total Labor Sale
\$0.00

Total Labor Cost
\$0.00

Total Parts Sale
\$0.00

Total Parts Cost
\$0.00

	Category	Sale	Cost
	Labor	\$0.00	\$6.30
	Parts	\$0.00	\$0.00
	Sublet	\$0.00	\$0.00
	Sublet Labor	\$0.00	\$0.00
	Sublet Parts	\$0.00	\$0.00
	Fees	\$0.00	\$0.00
	Discounts	\$0.00	-
	Tax	\$0.00	-
	Deductible	\$0.00	-
	Insurance/Warranty	\$0.00	-
	Invoice Total	\$0.00	\$6.30





1025 WI-77 Minong WI US 54859 www.linkrvdirect.com

Invoice
\$0.00

RO# : 39334 Tag# : T11P0067

Check-in: Thu Sep 11, 2025 | 2:44 PM
Ready for Pickup: Tue Apr 7, 2026 | 2:49 PM
Promise Time: Tue Sep 16, 2025 | 6:00 PM

Customer
linkautomotive - 2174
PD7155200709I
Customer
1235491
+1 - (715) 466 - 2222

Billing-Customer
Same as Customer

Vehicle
2026 JAYCO JAYLOFT
BUNGALOW
1UJBC0BV3T11P0067

Service Advisor
BECKY DALEIDEN
beckl

Clock In Info

#	Opcode	Date	Clock In	Clock Out	Time Spent	Pay Type	Technician	Flag Hrs
A	MISC	Wed Dec 10, 2025	2:55 PM	3:00 PM	0.08 hrs	W	matthewl	0.3 hrs
Tag: Regular Hour			Reason: -					
C	MISC	Wed Dec 10, 2025	3:00 PM	3:05 PM	0.10 hrs	W	matthewl	0 hrs
Tag: Regular Hour			Reason: -					
F	MISC	Wed Dec 10, 2025	3:06 PM	3:26 PM	0.33 hrs	W	matthewl	0 hrs
Tag: Regular Hour			Reason: -					
G	MISC	Wed Dec 10, 2025	3:40 PM	3:48 PM	0.13 hrs	W	matthewl	0 hrs
Tag: Regular Hour			Reason: -					
F	MISC	Wed Dec 10, 2025	3:48 PM	8:38 AM	16.82 hrs	W	matthewl	-
Tag: Regular Hour			Reason: -					
B	MISC	Thu Dec 11, 2025	8:42 AM	8:45 AM	0.06 hrs	W	matthewl	0 hrs
Tag: Regular Hour			Reason: -					
D	MISC	Thu Dec 11, 2025	8:45 AM	8:55 AM	0.16 hrs	W	matthewl	0 hrs
Tag: Regular Hour			Reason: -					
E	MISC	Thu Dec 11, 2025	8:55 AM	8:59 AM	0.08 hrs	W	matthewl	0 hrs
Tag: Regular Hour			Reason: -					





1025 WI-77 Minong WI US 54859 www.linkrvidirect.com

Invoice
\$0.00

RO# : 39334 Tag# : T11P0067

Check-in: Thu Sep 11, 2025 | 2:44 PM

Ready for Pickup: Tue Apr 7, 2026 | 2:49 PM

Promise Time: Tue Sep 16, 2025 | 6:00 PM

Customer

linkautomotive - 2174
PD7155200709I
Customer
1235491
+1 - (715) 466 - 2222

Billing-Customer

Same as Customer

Vehicle

2026 JAYCO JAYLOFT
BUNGALOW
1UJBC0BV3T11P0067

Service Advisor

BECKY DALEIDEN
beckl

Accounting Info - Warranty

GL Account #	Control #	Franchise	Amount
11400	39334	LINK RV	\$0.00
57200	39334	LINK RV	\$0.00
67200	39334	LINK RV	\$6.30
14400	matthewl	LINK RV	-\$6.30

