

FOREST RIVER WARRANTY CLAIM FORM

DEALER ACCOUNT #	1054928	CLAIM STATUS	Paid
LINK FORD & RV MINONG LLC		CLAIM	2644332
1025 W HOKAH ST		CLAIM ORIGIN	WEB
MINONG, WI 54859		ORIGINAL CLAIM ID	
USA		VIN	5ZT2AVPB1TB941913
		CHASSIS VIN	
		MILEAGE	0
Labor rate:	\$165.00	SITE/WAREHOUSE	050 / 050
OWNER INFORMATION		ITEM #	AVT25RBS
		DEALER RO #	40250
		CLAIM START DATE	04/16/2026
		CLAIM END DATE	04/16/2026

Retail Date of Purchase

WARRANTY EXPIRATION DATE

Claim Line Details

Labor

Line# 1	Operation Code	Operational Description		
	20-73-15-00-000745	Wheel Well Trim - Exterior/Fender Skirts/Wheel Well/Repair or Replace/No Tread Code		
	Complaint, Cause, Correction			
	Original Note : alix@dealer-advisors.com, 2026-04-16 12:18:49 :: This is a freight only claim that goes with 2607369. Complaint: Dealer states fabric above ODS front tire is ripped. Cause: Debris from tire cause holes in fabric above tire. Correction: Replace fabric. **FREIGHT ONLY CLAIM**			
Model#	Dlr Sub Hrs	0.00	Sub Labor Amt	\$0.00
Serial#	Appr Hrs	0.00	Appr Labor Amt	\$0.00
	Notes			

Part

Line# 1	Item #	Description				
	USERPART	Missed freight from invoice 14645953 - QTY 2 of F100697246 were used and I only charged freight for 1 of those.				
	Model #	Serial #	Part tag			
	Sub Qty	1.00	Sub Dlr Price	\$113.84	Sub Freight	\$0.00
	Appr Qty	1.00	Appr Dlr Price	\$113.84	Appr Freight	\$0.00
	Notes					

Submitted	Labor Amt	\$0.00	Approved	Labor Amt	\$0.00
	Parts & Freight	\$113.84		Parts & Freight	\$113.84
	Total	\$113.84		Total	\$113.84

DEALER	DATE
SIGNATURE	
I certify that I have performed these repairs consistent with Forest River Policies.	

CUSTOMER	DATE
SIGNATURE	
All repairs described have been inspected and are satisfactory.	