



Warranty Claim Detail

R.O. Number **71872A**
 Job **5**

COMPLAINT INFORMATION	
Flat Rate Code	1519
Description	String-KIB-Sensor Strings
Occurrences	1
Requested Hours	1.00
Authorized Hours	1.00
Fault Code	64-Production
Vendor Responsible	89996-NEWMAR WORKMANSHIP Hours:1.00

GENERAL INFORMATION	
Status	Paid
Date In	06/20/2025
Submit Date	03/16/2026
Authorization	No 03/17/2026
Work Complete	Yes 03/31/2026
Payment	Yes 04/10/2026

CUSTOMER COMPLAINT
COMMENT ENTERED ON 03/16/2026 AT 10:35 AM BY DEALER Clarified with Brian on this one - fresh tank has two sensors - both of the sensors were replaced. Per Phil, added a new job for the additional sensor. Requesting an additional 1.0 to account for both sensor replacements.
AUTHORIZATION NOTES
DEALER CORRECTION
COMMENT ENTERED ON 03/16/2026 AT 10:35 AM BY DEALER Replace sensor.

TOTALS	Requested	Authorized
Labor	185.00	185.00
Sublet	.00	.00
Parts	65.19	65.19
Freight	.00	.00
Adjustments	.00	.00
TOTAL	269.75	269.75
TOTAL PAID		269.75

