



12024 Central Ave SE ★ Albuquerque NM 87123
www.MYERSRV.com
(505)298-7691 ★ 1-800-748-2078 ★ FAX (505)293-7172

WO #: 73082A

Customer Name: 54085 - FLETCHER,
SASHA MICHELLE

Completed Date:
Invoice#:
Author: BRIAN
Stock Desc: 9575 2026 SANIBEL
38LAUNDRY
Serial#: 5ZT3SN3B7TG706104
Chassis#: 5ZT3SN3B7TG706104
Miles/Hrs:
Tag#:
Purchased Date: 26 MAR 26
Warranty Date: 26 MAR 26

Date In: 31 MAR 26
Time In:

Job #01 - Warranty

COMPLAINT: WARRANTY ITEM

CAUSE: Bed slide supports too far back and off center
Frame not completely secure to the slide

CORRECTION: Removed mattress
Disconnected the struts from the under bed storage
Removed both pieces of plywood
Unscrewed the bed frame from the slide room
Checked the bed supports by measurements and found they were too far back to support the foot of the bed and off center to the right
Moved the bed supports forward and put shims under them
Moved them to be centered under the bed
Set the bed frame back in place
Found the bed frame was screwed to the floor with 2 screws at the edge of the slide but nothing at the head of the bed
Added screws at the head of the bed
Completely reattached the bed frame back to the slide
Reinstalled the plywood and struts
Tested the bed on extend and retract and now stays well above the floor
Reattached the trim that was pulled off from dragging on the floor
Put the mattress back in place
REQUESTING 1.75

Labor

Job #	Description	Total
01	Master bed slide dragging on the floor when all the way retracted	N/C
Subtotal for Job #01:		0.00

Job #2 - Warranty

COMPLAINT: WARRANTY ITEM

CAUSE: Cabinet door misaligned

CORRECTION: Adjusted the doors under the sink , to the left of the microwave, the pantry. REQUESTING .40

W/O: 73082A
Promised Date:
06 MAR 26

73082A

Customer #: 54085
FLETCHER, SASHA
MICHELLE

54085

W/O: 73082A
Promised Date: 26 MAR 26

73082A

Customer #: 54085
FLETCHER, SASHA
MICHELLE

54085

Labor			Total
Job #	Description		N/C
2	MISC LABOUR CODE (WARRANTY)		
Subtotal for Job #2:			0.00

Job #3 - Internal

Transferred to RV*73082 on 31 MAR 26
Estimate amount was 0.00
REPAIR WALL PANEL

Labor				
Job #	Description			Total
3	WALL PANEL			N/C
Other Services				
Code	Description	Qty	Price	Total
SS-I	SHOP SUPPLIES - INTERNAL	0.00	N/C	N/C
Subtotal for Job #3:				0.00

Job #03 - Warranty

COMPLAINT: WARRANTY ITEM

CAUSE: Seam tape peeling off the wall in laundry room

CORRECTION: Removed seam tape and replaced with new seam tape
REQUESTING .20

Labor			Total
Job #	Description		N/C
03	Seam tape coming off the wall		
Subtotal for Job #03:			0.00

Job #04 - Warranty

COMPLAINT: WARRANTY ITEM

CAUSE: Plug with backer board fell off

CORRECTION: Moved the backer board over slightly rescrewed it to the floor
REQUESTING .15

Labor			Total
Job #	Description		N/C
04	Plug in basement fell off		
Subtotal for Job #04:			0.00

Job #05 - Warranty

COMPLAINT: WARRANTY ITEM

CAUSE: Dime size hole in the paneling

CORRECTION: Filled hole with silicone
Ran a strip of seam tape floor to ceiling over the hole
REQUESTING .10

Labor			Total
Job #	Description		N/C
05	Hole in the paneling at the entrance to the front bedroom		

W/O: 73082A
Promised Date: 26 MAR 26

73082A

Customer #: 54085
FLETCHER, SASHA
MICHELLE

54085

Subtotal for Job #05: 0.00

Job #5 - Warranty

COMPLAINT: UPPER CABINET DOOR WARPED

CAUSE: Wrapped door

CORRECTION: Recommend replacement

Door size 14 x30

REQUESTING .35

Labor

Job #	Description	Total
5	CABINET DOOR	N/C

Subtotal for Job #5: 0.00

Job #06 - Warranty

COMPLAINT: WARRANTY ITEM

CAUSE: Reported on delivery happened during transport

CORRECTION: Recommend replacement of the fender skirt and black J wrap 15 feet on passenger living slide

See attached photos

.40

Labor

Job #	Description	Total
06	Hole in J wrap and deep scratches in fender skirt	N/C

Subtotal for Job #06: 0.00

Job #7 - Warranty

COMPLAINT: WARRANTY ITEM

CAUSE: Door jam not square door will open past the stop trim

CORRECTION: Added shims under the jam got the jam square so the door will close properly.

Puttied all staple holes and nail holes

REQUESTING .30

Labor

Job #	Description	Total
7	MISC LABOUR CODE (WARRANTY)	N/C

Subtotal for Job #7: 0.00

Job #08 - Warranty

COMPLAINT: WARRANTY ITEM

CAUSE: Glass tray from microwave fell during transport

CORRECTION: Replace whole cabinet door

12 inches by 24 inches

REQUESTING .40

Labor

Job #	Description	Total
08	Hole in cabinet door	N/C

W/O: 73082A
Promised Date: 26 MAR 26

73082A

Customer #: 54085
FLETCHER, SASHA
MICHELLE

54085

Subtotal for Job #08: 0.00

Job #9 - Internal

COMPLAINT: Transferred to RV*73082 on 31 MAR 26

Estimate amount was 0.00

TPMS

CAUSE: Not programed

CORRECTION: Programmed

Work completed

Labor

Job #	Description	Total
9	TIRE PRESSURE MONITORING SYS INSTALL (PER WHEEL)	N/C

Subtotal for Job #9: 0.00

Job #10 - Warranty

COMPLAINT: WARRANTY ITEM

CAUSE: Couch slide blew two fuses on retract

CORRECTION: Replaced the fuse ran slide in and out several times could not replicate
REQUESTING .35

Labor

Job #	Description	Total
10	Livingoom slide couch side blowing fuses	N/C

Parts

Part #	Description	Qty	Price	Total
99-8106	BOARD REPAIR TAPE FOR UNDERBELLY - 1 FT	7.00	N/C	N/C
1706	ATC-30 FUSE	12.00	N/C	N/C
5121	ATC-40 FUSE	1.00	N/C	N/C

Subtotal for Job #10: 0.00

Job #11 - Warranty

COMPLAINT: WARRANTY ITEM

CAUSE: Range hood fell off during transport and broke the grate for the stove top
Actual top is also damaged next to the burner

CORRECTION: Parts will need to be replaced
See photos
REQUESTING .50

Labor

Job #	Description	Total
11	Stove top grate broken	N/C

Subtotal for Job #11: 0.00

Parts Total: 0.00

Labour Total: 0.00

Sublet Total: 0.00

Extras Total: 0.00

WORK ORDER TOTAL: 0.00

NOTICE:
DUE TO A LACK OF SPACE, A \$15/DAY STORAGE FEE WILL APPLY IF YOU DO NOT PICK UP YOUR UNIT WITHIN 48 HOURS OF NOTICE OF COMPLETION

EFFECTIVE 01/12/2026 A CREDIT CARD SURCHARGE OF 3% WILL BE APPLIED TO ALL CREDIT CARD TRANSACTIONS

MANUFACTURER'S WARRANTIES AND SERVICE CONTRACTS DO NOT COVER DIAGNOSTIC TIME IF NO PROBLEM IS FOUND

ALTHOUGH WE TAKE PRECAUTIONS TO INSURE YOUR VEHICLE'S SECURITY WHILE IN FOR REPAIRS, WE ARE NOT RESPONSIBLE FOR ANY LOSS OR DAMAGE TO THE VEHICLE OR CONTENTS DUE TO FIRE, THEFT, OR ANY OTHER CAUSE BEYOND OUR CONTROL. WE WOULD APPRECIATE YOUR ASSISTANCE BY REMOVING OR SECURING YOUR VALUABLES SUCH AS GUNS, CAMERAS, JEWELRY, CASH, ETC.

I hereby authorize Myers RV Center, Inc. to perform the repair work set forth in this work order, including the parts and materials necessary. I agree that you are not responsible for delays caused by unavailability of parts or delays in parts shipments by the supplier or transporter. I hereby grant you and/or your employees permission to operate the vehicle herein described on streets and highways for the purpose of testing, inspection or transporting to sublet vendors. An express mechanics lien is hereby acknowledged on the herein described vehicle to secure the payment for repairs performed.

Date: 31 Mar 2026

Customer Signature : _____

Customer Work Order

W/O: 73082A
Promised Date: 26 MAR 26

73082A

Customer #: 54085
FLETCHER, SASHA
MICHELLE

54085