

FOREST RIVER WARRANTY CLAIM FORM

DEALER ACCOUNT # 0008794
 MYERS RV CENTER INC
 12024 CENTRAL AVE S.E.
 ALBUQUERQUE, NM 87123
 USA

CLAIM STATUS Paid
 CLAIM 2502049
 CLAIM ORIGIN WEB
 ORIGINAL CLAIM ID
 VIN 5ZT2TRNB6TB526350
 CHASSIS VIN
 MILEAGE 0
 SITE/WAREHOUSE 048 / 048B
 ITEM # TRT235RK
 DEALER RO # 71969
 CLAIM START DATE 11/17/2025
 CLAIM END DATE 12/22/2025

Labor rate: \$190.00
 OWNER INFORMATION

Retail Date of Purchase WARRANTY EXPIRATION DATE

Claim Line Details

Labor

Line# 1 **Operation Code** **Operational Description**
 30-92-01-00-001191 Cutting Board - Interior/Interior Miscellaneous/Replace/No Tread Code
Complaint, Cause, Correction
 Original Note : ryliefayth@gmail.com, 2025-11-14 13:31:05 :: Cutting board/sink cover does not fit / Incorrect part / Cutting board measures 13 1/4 x 11 and three-quarter inches. Sink hole is 13 7/8 inches wide. Recommend cutting board be at the minimum 13 and three-quarter inches to 13 1/2 inches.

Model#	Dlr Sub Hrs	0.10	Sub Labor Amt	\$19.00
Serial#	Appr Hrs	0.00	Appr Labor Amt	\$0.00

Notes

This is for part only no labor per dealer's description. This authorization is pending ALL requirements of repair code have been met.

Part

Line# 1	Item #	Description			
	F100521445	SINK COVER, 11.75" X 13.25" BAMBOO SINK COVER (645725) U17, RACK A, FLOOR			
	Model #	Serial #	Part tag		
	Sub Qty	Sub Dlr Price	Sub Freight	Appr Qty	Appr Freight
	1.00	\$23.97	\$16.49	1.00	\$16.49
	Appr Qty	Appr Dlr Price	Appr Freight		
	1.00	\$23.97	\$16.49		

Notes

Submitted	Labor Amt	\$19.00	Approved	Labor Amt	\$0.00
	Parts & Freight	\$40.46		Parts & Freight	\$40.46
	Total	\$59.46		Total	\$40.46

DEALER _____ DATE _____
 SIGNATURE
 I certify that I have performed these repairs consistent with Forest River Policies.

CUSTOMER _____ DATE _____
 SIGNATURE
 All repairs described have been inspected and are satisfactory.