

FOREST RIVER WARRANTY CLAIM FORM

DEALER ACCOUNT #	0008794	CLAIM STATUS	Paid
MYERS RV CENTER INC		CLAIM	2533546
12024 CENTRAL AVE S.E.		CLAIM ORIGIN	WEB
ALBUQUERQUE, NM 87123		ORIGINAL CLAIM ID	
USA		VIN	4X4TRPU19TB035105
		CHASSIS VIN	
		MILEAGE	0
Labor rate:	\$190.00	SITE/WAREHOUSE	080 / 080
OWNER INFORMATION		ITEM #	RPT190-80
		DEALER RO #	72182
		CLAIM START DATE	12/22/2025
		CLAIM END DATE	12/26/2025

Retail Date of Purchase	WARRANTY EXPIRATION DATE
-------------------------	--------------------------

Claim Line Details

Labor

Line# 1	Operation Code	Operational Description		
	40-106-24-11-001253	Exterior 12 Volt Wiring - Electrical/12 Volt Exterior/Repair/Electrical		
	Complaint, Cause, Correction			
	Original Note : stephanie@dealer-advisors.com, 2025-12-22 09:02:27 :: Complaint: Wiring for the power jack has been cut Cause: Unit arrived this way, electric jack wires cut Correction: During the PDI found the wires to the electric jack were cut and ground wire was not connected. Used 24 inches of wire one butt splice and a connector for the battery post. Spliced together and screwed the ground to the tongue under an existing screw. Connected battery to unit and tested the jack.			
Model#	Dlr Sub Hrs	0.50	Sub Labor Amt	\$95.00
Serial#	Appr Hrs	0.50	Appr Labor Amt	\$95.00
	Notes			
	Authorized to repair as stated			

Part

Line# 1	Item #	Description		
	USERPART	24" of wire		
	Model #	Serial #	Part tag	
	Sub Qty	1.00	Sub Dlr Price	\$4.75
	Appr Qty	1.00	Appr Dlr Price	\$4.75
			Sub Freight	\$0.00
			Appr Freight	\$0.00
	Notes			

Submitted	Labor Amt	\$95.00	Approved	Labor Amt	\$95.00
	Parts & Freight	\$4.75		Parts & Freight	\$4.75
	Total	\$99.75		Total	\$99.75

DEALER	DATE
SIGNATURE	
I certify that I have performed these repairs consistent with Forest River Policies.	

CUSTOMER	DATE
SIGNATURE	
All repairs described have been inspected and are satisfactory.	