



12024 Central Ave SE ★ Albuquerque NM 87123
 www.MYERSRV.com
 (505)298-7691 ★ 1-800-748-2078 ★ FAX (505)293-7172

W/O: 71910
 Promised Date:



WO #: 71910
 Customer Name: 1000 - MYERS "RV"
 CENTER, INC.

Completed Date:
 Invoice#:
 Author: BRIAN
 Stock Desc: 9558 2026 BAY STAR 3225
 Serial#: 142199
 Chassis#: 1F66F5DN3S0A01256
 Miles/Hrs: 1454
 Tag#: NEED STOCK
 Purchased Date: 12 DEC 25
 Warranty Date: 27 DEC 25

Date In: 27 JUN 25
 Time In:

Job #1 - Internal
 CHECK IN UNIT.

Labor

Job #	Description	Total
1	CHECK IN UNIT	N/C

Other Services

Code	Description	Qty	Price	Total
SS-I	SHOP SUPPLIES - INTERNAL	1.00	N/C	N/C

Subtotal for Job #1: 0.00

Job #2 - Internal
 COMPLAINT: PRE-PDI

CAUSE: Pre

CORRECTION: Completed. See added jobs

Labor

Job #	Description	Total
2	PRE-PDI	N/C

Parts

Part #	Description	Qty	Price	Total
1000	L.P. GAS	25.00	N/C	N/C

Subtotal for Job #2: 0.00

Job #WIN-STD - Internal
 COMPLAINT: WINTERIZE STANDARD
 ADD FOR ICE MAKER

CAUSE: Winterize

CORRECTION: Completed. Note: unit has ice maker

Labor

Job #	Description	Total
WIN-STD	WINTERIZE RV - BASIC	N/C

Parts

Customer #: 1000
 MYERS "RV" CENTER,
 INC.,



W/O: 71910
Promised Date: 15 JUL 25

Part #	Description	Qty	Price	Total
21622	ANTIFREEZE	3.00	N/C	N/C

Other Services

Code	Description	Qty	Price	Total
SS	SHOP SUPPLIES	0.00	N/C	N/C

Subtotal for Job #WIN-STD: 0.00

Job #3 - Warranty

COMPLAINT: Driver side slide front window shade falling off brackets

CAUSE: Bracket detached

CORRECTION: Reattached and tested. Completed

Labor

Job #	Description	Total
3	WINDOW SHADE DIAGNOSE	74.00

Subtotal for Job #3: 74.00

Job #4 - Warranty

COMPLAINT: Kitchen sink window shade detached and laying on counter

CAUSE: Reinstall

CORRECTION: Completed

Labor

Job #	Description	Total
4	WINDOW SHADE DIAGNOSE	55.50

Subtotal for Job #4: 55.50

Job #5 - Warranty

COMPLAINT: Outside shower valve leaking

CAUSE: Leaking at weld point

CORRECTION: Replace order

Labor

Job #	Description	Total
5	OUTSIDE SHOWER LEAK DIAGNOSE	42.55

Subtotal for Job #5: 42.55

Job #6 - Warranty

COMPLAINT: Sealant cracking around shower skylight on roof

CAUSE: Clean and reseal

CORRECTION: Completed

Labor

Job #	Description	Total
6	ROOF SEALANT SPOT SEAL TOUCH UP SEALANT	92.50

Parts

Part #	Description	Qty	Price	Total
49329	DICOR SELF-LEVELING---SEALANT F/EPDM ROOFS	2.00	8.39	16.78

Customer #: 1000
MYERS "RV" CENTER,
INC.,



Subtotal for Job #6: 109.28

Job #7 - Warranty

COMPLAINT: Front hood latch not opening hood

CAUSE: Dry and painted.

CORRECTION: Cleaned off paint from latch and lubricated. Tested. Completed

Labor

Job #	Description	Total
7	MOTOR COVER LATCH ADJUST	37.00

Subtotal for Job #7: 37.00

Job #8 - Warranty

COMPLAINT: Bedroom slide out very loud and squealing

CAUSE: Rollers dry. Removed bed access panels to get to rollers

CORRECTION: Lubricated all rollers. Reassembled bed access. Tested. Completed

Labor

Job #	Description	Total
8	SLIDE OUT ROOM DIAGNOSTIC TIME	185.00

Subtotal for Job #8: 185.00

Parts Total: 16.78
 Labour Total: 486.55
 Sublet Total: 0.00
 Extras Total: 0.00

WORK ORDER TOTAL: 503.33

NOTICE:
DUE TO A LACK OF SPACE, A \$15/DAY STORAGE FEE WILL APPLY IF YOU DO NOT PICK UP YOUR UNIT WITHIN 48 HOURS OF NOTICE OF COMPLETION

MANUFACTURER'S WARRANTIES AND SERVICE CONTRACTS DO NOT COVER DIAGNOSTIC TIME IF NO PROBLEM IS FOUND

ALTHOUGH WE TAKE PRECAUTIONS TO INSURE YOUR VEHICLE'S SECURITY WHILE IN FOR REPAIRS, WE ARE NOT RESPONSIBLE FOR ANY LOSS OR DAMAGE TO THE VEHICLE OR CONTENTS DUE TO FIRE, THEFT, OR ANY OTHER CAUSE BEYOND OUR CONTROL. WE WOULD APPRECIATE YOUR ASSISTANCE BY REMOVING OR SECURING YOUR VALUABLES SUCH AS GUNS, CAMERAS, JEWELRY, CASH, ETC.

I hereby authorize Myers RV Center, Inc. to perform the repair work set forth in this work order, including the parts and materials necessary. I agree that you are not responsible for delays caused by unavailability of parts or delays in parts shipments by the supplier or transporter. I hereby grant you and/or your employees permission to operate the vehicle herein described on streets and highways for the purpose of testing, inspection or transporting to sublet vendors. An express mechanics lien is hereby acknowledged on the herein described vehicle to secure the payment for repairs performed.

Date: 15 Dec 2025

Customer Signature : _____

W/O: 71910
Promised Date: 15 JUL 25



Customer #: 1000
MYERS "RV" CENTER,
INC.,

