



12024 Central Ave SE ★ Albuquerque NM 87123  
 www.MYERSRV.com  
 (505)298-7691 ★ 1-800-748-2078 ★ FAX (505)293-7172

W/O: 71910  
 Promised Date:



WO #: 71910

Customer Name: 1000 - MYERS "RV"  
 CENTER, INC.

Completed Date:  
 Invoice#:  
 Author: BRIAN  
 Stock Desc: 9558 2026 BAY STAR 3225  
 Serial#: 142199  
 Chassis#: 1F66F5DN3S0A01256  
 Miles/Hrs: 1454  
 Tag#: NEED STOCK  
 Purchased Date: 12 DEC 25  
 Warranty Date: 27 DEC 25

Date In: 27 JUN 25  
 Time In:

**Job #1 - Internal**

CHECK IN UNIT.

**Labor**

Job #	Description	Total
1	CHECK IN UNIT	N/C

**Other Services**

Code	Description	Qty	Price	Total
SS-I	SHOP SUPPLIES - INTERNAL	1.00	N/C	N/C

**Subtotal for Job #1: 0.00**

**Job #2 - Internal**

COMPLAINT: PRE-PDI

CAUSE: Pre

CORRECTION: Completed. See added jobs

**Labor**

Job #	Description	Total
2	PRE-PDI	N/C

**Parts**

Part #	Description	Qty	Price	Total
1000	L.P. GAS	25.00	N/C	N/C

**Subtotal for Job #2: 0.00**

**Job #WIN-STD - Internal**

COMPLAINT: WINTERIZE STANDARD  
 ADD FOR ICE MAKER

CAUSE: Winterize

CORRECTION: Completed. Note: unit has ice maker

**Labor**

Job #	Description	Total
WIN-STD	WINTERIZE RV - BASIC	N/C

**Parts**

Customer #: 1000  
 MYERS "RV" CENTER,  
 INC.,





Part #	Description	Qty	Price	Total
21622	ANTIFREEZE	3.00	N/C	N/C

**Other Services**

Code	Description	Qty	Price	Total
SS	SHOP SUPPLIES	0.00	N/C	N/C

**Subtotal for Job #WIN-STD: 0.00**

**Job #3 - Warranty**

COMPLAINT: Driver side slide front window shade falling off brackets

CAUSE: Bracket detached

CORRECTION: Reattached and tested. Completed

**Labor**

Job #	Description	Total
3	WINDOW SHADE DIAGNOSE	N/C

**Subtotal for Job #3: 0.00**

**Job #4 - Warranty**

COMPLAINT: Kitchen sink window shade detached and laying on counter

CAUSE: Reinstall

CORRECTION: Completed

**Labor**

Job #	Description	Total
4	WINDOW SHADE DIAGNOSE	N/C

**Subtotal for Job #4: 0.00**

**Job #5 - Warranty**

COMPLAINT: Outside shower valve leaking

CAUSE: Leaking at weld point

CORRECTION: Replace order

**Labor**

Job #	Description	Total
5	OUTSIDE SHOWER LEAK DIAGNOSE	N/C

**Subtotal for Job #5: 0.00**

**Job #6 - Warranty**

COMPLAINT: Sealant cracking around shower skylight on roof

CAUSE: Clean and reseal

CORRECTION: Completed

**Labor**

Job #	Description	Total
6	ROOF SEALANT SPOT SEAL TOUCH UP SEALANT	N/C

**Parts**

Part #	Description	Qty	Price	Total
49329	DICOR SELF-LEVELING---SEALANT F/EPDM ROOFS	2.00	N/C	N/C



W/O: 71910  
Promised Date: 15 JUL 25



Customer #: 1000  
MYERS "RV" CENTER,  
INC.,



Subtotal for Job #6: 0.00

**Job #7 - Warranty**

COMPLAINT: Front hood latch not opening hood

CAUSE: Dry and painted.

CORRECTION: Cleaned off paint from latch and lubricated. Tested. Completed

**Labor**

Job #	Description	Total
7	MOTOR COVER LATCH ADJUST	N/C

Subtotal for Job #7: 0.00

**Job #8 - Warranty**

COMPLAINT: Bedroom slide out very loud and squealing

CAUSE: Rollers dry. Removed bed access panels to get to rollers

CORRECTION: Lubricated all rollers. Reassembled bed access. Tested. Completed

**Labor**

Job #	Description	Total
8	SLIDE OUT ROOM DIAGNOSTIC TIME	N/C

Subtotal for Job #8: 0.00

Customer Order

Parts Total: 0.00  
 Labour Total: 0.00  
 Sublet Total: 0.00  
 Extras Total: 0.00  
**WORK ORDER TOTAL: 0.00**

NOTICE:  
DUE TO A LACK OF SPACE, A \$15/DAY STORAGE FEE WILL APPLY IF YOU DO NOT PICK UP YOUR UNIT WITHIN 48 HOURS OF NOTICE OF COMPLETION

\*\*MANUFACTURER'S WARRANTIES AND SERVICE CONTRACTS DO NOT COVER DIAGNOSTIC TIME IF NO PROBLEM IS FOUND\*\*

ALTHOUGH WE TAKE PRECAUTIONS TO INSURE YOUR VEHICLE'S SECURITY WHILE IN FOR REPAIRS, WE ARE NOT RESPONSIBLE FOR ANY LOSS OR DAMAGE TO THE VEHICLE OR CONTENTS DUE TO FIRE, THEFT, OR ANY OTHER CAUSE BEYOND OUR CONTROL. WE WOULD APPRECIATE YOUR ASSISTANCE BY REMOVING OR SECURING YOUR VALUABLES SUCH AS GUNS, CAMERAS, JEWELRY, CASH, ETC.

I hereby authorize Myers RV Center, Inc. to perform the repair work set forth in this work order, including the parts and materials necessary. I agree that you are not responsible for delays caused by unavailability of parts or delays in parts shipments by the supplier or transporter. I hereby grant you and/or your employees permission to operate the vehicle herein described on streets and highways for the purpose of testing, inspection or transporting to sublet vendors. An express mechanics lien is hereby acknowledged on the herein described vehicle to secure the payment for repairs performed.

Date: 16 Dec 2025

Customer Signature : \_\_\_\_\_

