



12024 Central Ave SE ★ Albuquerque NM 87123
 www.MYERSRV.com
 (505)298-7691 ★ 1-800-748-2078 ★ FAX (505)293-7172

W/O: 72803-1
 Promised Date:
 06 JAN 26



WO #: 72803-1

Customer Name: 61048 - TORRES,
 STEPHANIE LEE

Completed Date: 23 JAN 26
 Invoice#:
 Author: BRIAN
 Stock Desc: 9534 2025 OPEN RANGE
 20FBS
 Serial#: 58TBM0BK5S75C3107
 Chassis#: 58TBM0BK5S75C3107
 Miles/Hrs:
 Tag#:
 Purchased Date: 06 JAN 26
 Warranty Date: 06 JAN 26

Date In: 05 JAN 26
 Time In:

Job #1 - Warranty

COMPLAINT: Passenger side fender skirt cracked needs to be replaced

CAUSE: SCREWS TOO TIGHT

CORRECTION: REMOVE AND REPLACE FENDERSKIRT
 .20HRS

Labor

Job #	Description	Total
1	REPLACE FENDERSKIRT	N/C

Parts

Part #	Description	Qty	Price	Total
0321158	FENDER SKIRT 66.13 X 9.5 BLACK HDHE	1.00	N/C	N/C

Subtotal for Job #1: 0.00

Parts Total: 0.00
 Labour Total: 0.00
 Sublet Total: 0.00
 Extras Total: 0.00
WORK ORDER TOTAL: 0.00

NOTICE:
 DUE TO A LACK OF SPACE, A \$15/DAY STORAGE FEE WILL APPLY IF YOU DO NOT PICK UP YOUR UNIT WITHIN 48 HOURS OF NOTICE OF COMPLETION

EFFECTIVE 01/12/2026 A CREDIT CARD SURCHARGE OF 3% WILL BE APPLIED TO ALL CREDIT CARD TRANSACTIONS

MANUFACTURER'S WARRANTIES AND SERVICE CONTRACTS DO NOT COVER DIAGNOSTIC TIME IF NO PROBLEM IS FOUND

ALTHOUGH WE TAKE PRECAUTIONS TO INSURE YOUR VEHICLE'S SECURITY WHILE IN FOR REPAIRS, WE ARE NOT RESPONSIBLE FOR ANY LOSS OR DAMAGE TO THE VEHICLE OR CONTENTS DUE TO FIRE, THEFT, OR ANY OTHER CAUSE BEYOND OUR CONTROL. WE WOULD APPRECIATE YOUR ASSISTANCE BY REMOVING OR SECURING YOUR VALUABLES SUCH AS GUNS, CAMERAS, JEWELRY, CASH, ETC.

I hereby authorize Myers RV Center, Inc. to perform the repair work set forth in this work order, including the parts and materials necessary. I agree that you are not responsible for delays caused by unavailability of parts or delays in parts shipments by the supplier or transporter. I hereby grant you and/or your employees permission to operate the vehicle herein described on streets and highways for the purpose of testing, inspection or transporting to sublet vendors. An express mechanics lien is hereby acknowledged on the herein described vehicle to secure the payment for repairs performed.

Customer #: 61048
 TORRES, STEPHANIE LEE



Customer Signature : _____

Date: 23 Jan 2026

W/O: 72803-1
Promised Date: 06 JAN 26



Customer #: 61048
TORRES, STEPHANIE LEE



Customer Work
Order

