

FOREST RIVER WARRANTY CLAIM FORM

DEALER ACCOUNT # 0008794		CLAIM STATUS	Paid
MYERS RV CENTER INC		CLAIM	2534696
12024 CENTRAL AVE S.E.		CLAIM ORIGIN	WEB
ALBUQUERQUE, NM 87123		ORIGINAL CLAIM ID	
USA		VIN	5ZT3CSPB3SG128152
		CHASSIS VIN	
		MILEAGE	0
Labor rate:	\$190.00	SITE/WAREHOUSE	049 / 049B
OWNER INFORMATION		ITEM #	CSF250RLX
DIANA STOW		DEALER RO #	72769
503 TRUJILLO ST #A		CLAIM START DATE	12/23/2025
Los Lunas, NM 87031		CLAIM END DATE	02/02/2026
USA			
Retail Date of Purchase	06/28/2025	WARRANTY EXPIRATION DATE	06/28/2026

Claim Line Details

Labor

Line# 1	Operation Code 20-43-01-00-000589	Operational Description Die Cut, Stripe, Decal, Graphic - Exterior/Exterior Miscellaneous/Replace/No Tread Code
Complaint, Cause, Correction		
Original Note : stephanie@dealer-advisors.com, 2025-12-23 10:03:17 :: Complaint: There are many decals that have bubbles Cause: Decals are bubbling. Found one decal at drivers rear lower black stripe bubble 3 1/2x48, 2 decals at drivers side front top, the black stripe is bubbling tapered 4 1/2 at the front 1 1/2 at the rear and 12 feet long. Three decals on the passenger side, same decal at drivers side #2. Correction: Attempted to smooth the bubbles out, the decals are already stretched out and will not lay back down without creases or wrinkles. Recommend replacement of decals. This will require removing each decal and cleaning the surface. The decal on the drivers side rear will require removing the shore cord plug and placing the decal on and then reinstalling the shore cord plug. Decal 2 on driver side front will require fitting it around the window. Decal 3 at passenger side front will require fitting it around the window and under the awning mounting bracket. Requesting 3.0 hours for all decals.		
Model#	Dlr Sub Hrs 3.00	Sub Labor Amt \$570.00
Serial#	Appr Hrs 3.00	Appr Labor Amt \$570.00
Notes		
I authorize the time that the dealer is requesting for replacement this is approved as described by the dealer. This authorization is pending ALL requirements of repair code have been met.		

Part

Line# 1	Item #	Description				
	F100600411	GRAPHIC, CRUSADER X 2025, DC 1 LH, 153386				
	Model #	Serial #	Part tag			
	Sub Qty	1.00	Sub Dlr Price	\$13.55	Sub Freight	\$44.40
	Appr Qty	1.00	Appr Dlr Price	\$13.55	Appr Freight	\$44.40
	Notes					
Line# 2	Item #	Description				
	F100600412	GRAPHIC, CRUSADER X 2025, DC 1 RH, 153387				
	Model #	Serial #	Part tag			
	Sub Qty	1.00	Sub Dlr Price	\$13.55	Sub Freight	\$0.00
	Appr Qty	1.00	Appr Dlr Price	\$13.55	Appr Freight	\$0.00
	Notes					
Line# 3	Item #	Description				
	F100600746	GRAPHIC, CRUSADER X 2025, DC 11 LH, 153406				
	Model #	Serial #	Part tag			

Sub Qty 1.00
Appr Qty 1.00

Sub Dlr Price \$13.51
Appr Dlr Price \$13.51

Sub Freight \$0.00
Appr Freight \$0.00

Notes

Submitted

Labor Amt \$570.00
Parts & Freight \$85.01
Total \$655.01

Approved

Labor Amt \$570.00
Parts & Freight \$85.01
Total \$655.01

DEALER

DATE

SIGNATURE

I certify that I have performed these repairs consistent with Forest River Policies.

CUSTOMER

DATE

SIGNATURE

All repairs described have been inspected and are satisfactory.