



12024 Central Ave SE ★ Albuquerque NM 87123
www.MYERSRV.com
(505)298-7691 ★ 1-800-748-2078 ★ FAX (505)293-7172

W/O: 72840
Promised Date:
16 JAN 26



WO #: 72840 (Appointment Date: 16 JAN 2026 - Time: 10:15am)

Customer Name: 59976 - GONZALES
JR, BENITO E

Completed Date:
Invoice#:
Author: BRIAN
Stock Desc: 9444 2025 CRUSADER
270BHX
Serial#: 5ZT3CSSB0SG128181
Chassis#: 5ZT3CSSB0SG128181
Miles/Hrs:
Tag#: 6987
Purchased Date: 28 MAY 25
Warranty Date: 28 MAY 25

Date In: 16 JAN 26

Time In:

Job #1 - Warranty

COMPLAINT: CUSTOMER STATES WHEN RAISING TRAILER WATER RUNS OUT FROM UNDERBELLY

CAUSE: Had to dewinterize unit. Couldnt duplicate customer complaint

CORRECTION: Pressure filled fresh tank. Ran all receptacles and filled holding tanks to test for leaks. Black tank was 3/4 full when unit arrived. Emptied tanks and tested for leaks. Let unit sit pressurized overnight. No water ever came out of underbelly. Couldnt duplicate customer complaint. Requesting straight time.

Labor

Job #	Description	Total
1	WATER SYSTEM TROUBLESHOOT	N/C

Other Services

Code	Description	Qty	Price	Total
SS	SHOP SUPPLIES	1.00	N/C	N/C

Subtotal for Job #1: 0.00

Job #2 - Warranty

COMPLAINT: CUSTOMER STATES PASSENGER SIDE USB PORT INOP AT BED

CAUSE: Couldnt duplicate

CORRECTION: All usb ports have power. Couldnt duplicate. Inspected both bedrooms. See pics for test

Labor

Job #	Description	Total
2	ELECTRICAL REPAIR	N/C

Subtotal for Job #2: 0.00

Job #3 - Warranty

COMPLAINT: CUSTOMER STATES REAR STABILIZER WILL NOT RETRACT PROPERLY. MUST OPERATE AND MOVE SWITCH TO GET THEM TO OPERATE.

CAUSE: Couldnt duplicate

CORRECTION: Tested switch, motor and verified proper voltages and amperages. Ran jacks several times

Customer #: 59976
GONZALES JR, BENITO E



in/out. Couldnt duplicate.

Labor		
Job #	Description	Total
3	REPAIR STABILIZERS	N/C
Subtotal for Job #3:		0.00

Job #4 - Warranty

COMPLAINT: CUSTOMER STATES HALLWAY MOTION LIGHT AT STAIRS INOP

CAUSE: Oxidized terminal at switch

CORRECTION: Removed wiring. Cleaned terminals and reinstalled switch. Tested function. Completed
Requesting.3hr

Labor		
Job #	Description	Total
4	ELECTRICAL REPAIR	N/C
Subtotal for Job #4:		0.00

Job #5 - Warranty

COMPLAINT: CUSTOMER STATES DRIVER'S SIDE REAR SLIDE RUBBING ON FLOOR / NOT FLUSH
AT EXTERIOR (RUBS ON FENDERSKIRT)

CAUSE: Out of adjustment.

CORRECTION: Performed leveling and stabilizing of coach to ensure accurate adjustments. Raised height
of rear floor to max position. Tested for clearance. Completed
Requesting.5 hr

Labor		
Job #	Description	Total
5	SLIDE OUT ROOM DIAGNOSTIC TIME	N/C
Subtotal for Job #5:		0.00

Job #6 - Warranty

COMPLAINT: DOCKING STATION DOOR MISSING ONE FLIP DOOR WITHIN THE DOOR.

CAUSE: Unknown missing

CORRECTION: Order and replace
.3

Labor		
Job #	Description	Total
6	DOOR COVER	N/C
Subtotal for Job #6:		0.00

Job #WIN-STD - External

COMPLAINT: WINTERIZE STANDARD

CAUSE: Winterize

CORRECTION: Completed

Labor		
Job #	Description	Total
WIN-STD	WINTERIZE RV - BASIC	175.00

Parts				
Part #	Description	Qty	Price	Total
21622	ANTIFREEZE	3.00	7.45	22.35

W/O: 72840
Promised Date: 30 JAN 26



Customer #: 59976
GONZALES JR, BENITO E



Other Services

Code	Description	Qty	Price	Total
SS	SHOP SUPPLIES	0.00	20.00	0.00

Subtotal for Job #WIN-STD: 197.35

Parts Total: 22.35
 Labour Total: 175.00
 Sublet Total: 0.00
 Extras Total: 0.00
 Tax Total: 15.05
WORK ORDER TOTAL: 212.40

NOTICE:
 DUE TO A LACK OF SPACE, A \$15/DAY STORAGE FEE WILL APPLY IF YOU DO NOT PICK UP YOUR UNIT WITHIN 48 HOURS OF NOTICE OF COMPLETION

EFFECTIVE 01/12/2026 A CREDIT CARD SURCHARGE OF 3% WILL BE APPLIED TO ALL CREDIT CARD TRANSACTIONS

MANUFACTURER'S WARRANTIES AND SERVICE CONTRACTS DO NOT COVER DIAGNOSTIC TIME IF NO PROBLEM IS FOUND

ALTHOUGH WE TAKE PRECAUTIONS TO INSURE YOUR VEHICLE'S SECURITY WHILE IN FOR REPAIRS, WE ARE NOT RESPONSIBLE FOR ANY LOSS OR DAMAGE TO THE VEHICLE OR CONTENTS DUE TO FIRE, THEFT, OR ANY OTHER CAUSE BEYOND OUR CONTROL. WE WOULD APPRECIATE YOUR ASSISTANCE BY REMOVING OR SECURING YOUR VALUABLES SUCH AS GUNS, CAMERAS, JEWELRY, CASH, ETC.

I hereby authorize Myers RV Center, Inc. to perform the repair work set forth in this work order, including the parts and materials necessary. I agree that you are not responsible for delays caused by unavailability of parts or delays in parts shipments by the supplier or transporter. I hereby grant you and/or your employees permission to operate the vehicle herein described on streets and highways for the purpose of testing, inspection or transporting to sublet vendors. An express mechanics lien is hereby acknowledged on the herein described vehicle to secure the payment for repairs performed.

Customer Signature : _____

Date: 27 Jan 2026

W/O: 72840
 Promised Date: 30 JAN 26



Customer #: 59976
 GONZALES JR, BENITO E

