

# FOREST RIVER WARRANTY CLAIM FORM

DEALER ACCOUNT # 0008794  
 MYERS RV CENTER INC  
 12024 CENTRAL AVE S.E.  
 ALBUQUERQUE, NM 87123  
 USA

CLAIM STATUS Paid  
 CLAIM 2548143  
 CLAIM ORIGIN WEB  
 ORIGINAL CLAIM ID  
 VIN 4X4TRPU1XTB035128  
 CHASSIS VIN  
 MILEAGE 0  
 SITE/WAREHOUSE 080 / 080  
 ITEM # RPT192-80  
 DEALER RO # 72186  
 CLAIM START DATE 01/12/2026  
 CLAIM END DATE 02/19/2026

Labor rate: \$190.00  
 OWNER INFORMATION

Retail Date of Purchase WARRANTY EXPIRATION DATE

## Claim Line Details

### Labor

**Line# 1**      **Operation Code**      **Operational Description**  
 40-106-24-11-001253      Exterior 12 Volt Wiring - Electrical/12 Volt Exterior/Repair/Electrical  
**Complaint, Cause, Correction**  
 Original Note : stephanie@dealer-advisors.com, 2026-01-12 14:53:45 :: Complaint: Awning lights are not working  
 Cause: Awning light switch is not working because the wires are not connected Correction: Corrected all wires to awning lights

<b>Model#</b>	<b>Dlr Sub Hrs</b>	0.20	<b>Sub Labor Amt</b>	\$38.00
<b>Serial#</b>	<b>Appr Hrs</b>	0.20	<b>Appr Labor Amt</b>	\$38.00

**Notes**  
 authorized to repair as stated

### Labor

**Line# 2**      **Operation Code**      **Operational Description**  
 40-196-01-11-001296      12 Volt Fuse - Electrical/12 Volt Interior/Replace/Electrical  
**Complaint, Cause, Correction**  
 Original Note : stephanie@dealer-advisors.com, 2026-01-12 14:55:30 :: Complaint: Water heater is not working  
 Cause: Water heater does not turn on due to a fuse being missing Correction: Replace 7 amp fuse inside of water heater

<b>Model#</b>	<b>Dlr Sub Hrs</b>	0.20	<b>Sub Labor Amt</b>	\$38.00
<b>Serial#</b>	<b>Appr Hrs</b>	0.20	<b>Appr Labor Amt</b>	\$38.00

**Notes**  
 authorized to replace fuse as stated

### Part

**Line# 1**      **Item #**      **Description**  
 USERPART      18637 7 amp mini glass fuse

<b>Model #</b>	<b>Serial #</b>	<b>Part tag</b>	
<b>Sub Qty</b> 1.00	<b>Sub Dlr Price</b> \$0.05	<b>Sub Freight</b>	\$0.00
<b>Appr Qty</b> 1.00	<b>Appr Dlr Price</b> \$0.05	<b>Appr Freight</b>	\$0.00

**Notes**

### Labor

**Line# 3**      **Operation Code**      **Operational Description**  
 60-140-01-00-001570      Bathroom (Lav) Sink - Plumbing/Bathroom (Lavatory) Sink/Replace/No Tread Code  
**Complaint, Cause, Correction**  
 Original Note : stephanie@dealer-advisors.com, 2026-01-12 14:56:22 :: Complaint: Bathroom sink has scuff marks Cause: Sink inside of bathroom is scuffed Correction: Replace sink

<b>Model#</b>	<b>Dlr Sub Hrs</b>	1.00	<b>Sub Labor Amt</b>	\$190.00
<b>Serial#</b>	<b>Appr Hrs</b>	0.50	<b>Appr Labor Amt</b>	\$95.00

